

Request for Qualifications (Architect / Engineer)

State of Ohio Standard Forms and Documents

Administration of Project: Local Higher Education

Project Name	<u>Perry Stadium Phase II Renovations</u>	Response Deadline	<u>10/23/15</u>	<u>2:00 pm</u>	local time
Project Location	<u>Bowling Green State University</u>	Project Number	<u>BGU-156153</u>		
City / County	<u>Bowling Green / Wood</u>	Project Manager	<u>Brian Swope</u>		
Owner	<u>Bowling Green State University</u>	Contracting Authority	<u>Local Higher Education</u>		
Delivery Method	<u>N/A</u>	Prevailing Wages	<u>State</u>		
No. of paper copies requested (stapled, not bound)	<u>3</u>	No. of electronic copies requested on CD (PDF)	<u>1</u>		

Submit the requested number of Statements of Qualifications (Form F110-330) directly to Beth Nagel at BGSU Purchasing Office, 1851 N Research Drive, Bowling Green, Ohio 43403. See Section H of this RFQ for additional submittal instructions.

Submit all questions regarding this RFQ in writing to Beth Nagel at bnagel@bgsu.edu with the project number included in the subject line (no phone calls please). Questions will be answered and posted to the Opportunities page on the OFCC website at <http://ofcc.ohio.gov> on a regular basis until one week before the response deadline. The name of the party submitting a question will not be included on the Q&A document.

Project Overview

A. Project Description

Bowling Green State University (the "Owner") is requesting interested firms to submit qualifications to prepare concept documents and imagery for Perry Stadium Phase II Renovations.

Bowling Green State University Department of Athletics is interested in enhancing the functionality and overall fan experience for Perry Stadium. Project will require donor funds and to facilitate this effort concept drawings and images for a revitalized stadium are necessary. A detailed scope of project is articulated under "Scope of Services" portion of this Request for Qualifications.

A Facilities Condition Report for the stadium was completed in 2009. A copy of this report is included herewith.

The stadium is currently embarking upon the Phase I Renovations that include (a) structural repairs, (b) waterproofing seat deck, (c) roof repairs and/or replacements, (d) visitor locker room expansion and remodel, and (e) cosmetic repairs to west press box and club seating. Drawings of this project are included herewith.

B. Scope of Services

The selected Architect/Engineer (A/E), as a portion of its required Scope of Services and prior to submitting its proposals, will discuss and clarify with the Owner, the cost breakdown of the Architect/Engineer Agreement detailed cost components to address the Owner's project requirements. Participation in the Encouraging Growth, Diversity & Equity (EDGE) Program as required by statute and the Agreement is expected.

As required by the Agreement, and as properly authorized, provide for participation in the following categories: Organizational Meeting, and Program Verification Stage. Additional Services will be discussed as necessary during the negotiation phase. Reimbursable Expenses will be approved per the Agreement.

Refer to the *OFC Manual* and/or the *Ohio School Design Manual* for additional information about the type and extent of services required for each. A copy of the standard Agreement can be obtained at the OFCC website at <http://ofcc.ohio.gov>. Note that all respondents to this RFQ will be responsible for, and held to, the terms of the standard Agreement and Exhibits as completed by the Owner. Any clarification or requested modifications to the same should be identified in the Respondent's response to this RFQ. No modifications to the requirements in the Agreement or Exhibits will be accepted at time of negotiation or technical proposal.

The current intent for the Phase II Renovations are: (a) improving tailgate/entry experience, (b) improving fan experience within stadium (e.g. concession areas, restrooms, bowl seating, viewing opportunities, social spaces, and retail environments), (c) expansion/renovation of suites, club seats and press box, (d) office and indoor seating improvements, (e) elevator and service upgrades, (f) creating multi-purpose spaces sized to host functions and retreats, (g) technology platform upgrades, and (h) exterior façade improvements.

Request for Qualifications (Architect / Engineer) continued

- Previous experience compatible with the proposed project (e.g., type, size).
- Relevant past work of prospective firm's proposed consultants.
- Past performance of prospective firm and its proposed consultants.
- Qualifications and experience of individuals directly involved with the project.
- Proposer's previous experience (numbers of projects, sizes of projects) when working with its proposed consultants.
- Proximity of prospective firms to the project site.

Interested A/E firms are required to address how they will implement Building Information Modeling ("BIM") on the project, experience and level of training of staff related to BIM, incorporation of team partners that have previous BIM experience, and an understanding of collaborative BIM processes, including but not limited to the *State of Ohio BIM Protocol* available at the OFCC website at <http://ofcc.ohio.gov>.

Interested A/E firms are required to submit the Commitment to Participate in the EDGE Business Assistance Program form in its Statement of Qualifications (Form F110-330) submitted in response to the RFQ, to indicate its intent to contract with and use EDGE-certified Business Enterprise(s), as a part of the A/E's team. The Intent to Contract and to Perform and / or waiver request letter and Demonstration of Good Faith Effort form(s) with complete documentation must be attached to the A/E's Technical Proposal. Both forms can be accessed via the OFCC website at <http://ofcc.ohio.gov>. The Intent to Contract and to Perform form is again required at the Fee Proposal stage.

For all Statements of Qualifications, please identify the EDGE-certified Business Enterprises, by name, which will participate in the delivery of the proposed professional services solicited in the RFQ.

H. RFQ Evaluation Schedule

Activity	Date
RFQ Responses Due:	October 23, 2015
Short-Listed Firms Notified	October 27, 2015
Interview Date	November 02, 2015
Preferred Firm Selection	November 02, 2015
Contract Award	November 04, 2015

I. Submittal Instructions

Firms are required to submit the current version of Statement of Qualifications (Form F110-330) available via the OFCC website at <http://ofcc.ohio.gov>.

Proposers shall also organize the RFQ response in such a manner that clearly documents team proficiency for each item stipulated as Selection Criteria on the CM at Risk Selection Rating Form. As an example the RFQ response can be indexed or tab denoting each of the sixteen (16) selection criteria.

(3) Paper copies of the Statement of Qualifications, submittals should be stapled. Do not use special bindings or coverings of any type. Cover letters and transmittals are not necessary.

Electronic submittals (Flash Drive preferred) should be combined into one PDF file named with the project number listed on the RFQ and your firm's name. Use the "print" feature of Adobe Acrobat Professional or similar software for creating a PDF rather than using a scanner. If possible, please reduce the file size of the PDF. In Adobe Acrobat Professional, go to Advanced, then PDF Optimizer. Also, please label the CD and the CD cover with the project number and firm name.

Facsimile or e-mailed copies of the Statement of Qualifications will not be accepted.

Submit all questions regarding this RFQ in writing to Beth Nagel at bnagel@bgsu.edu with the project number included in the subject line (**no phone calls please**). Questions will be answered and posted to the BGSU Purchasing Department website at <http://www.bgsu.edu/offices/purchasing/page85370.html> and/or OAKS Capital Improvements (OAKS CI) website at <http://ci.oaks.ohio.gov> on a regular basis until two days before the response deadline. The name of the party submitting a question will not be included on the Q&A document.

Firms are requested to identify professional registrations, memberships and credentials including but not limited to: LEED GA, LEED AP, LEED AP+, CCCA, CCM, CCS, CDT, DBIA, CPE, and any other appropriate design and construction industry credentials. Identify that information on the resume page for individual in Block 22, Section E of the F110-330 form.

Architect/Engineer Selection Rating Form

State of Ohio Standard Forms and Documents

Project Name Perry Stadium Phase II Renovations Proposer Firm _____
 Project Number BGU-156153 City, State, Zip _____

Selection Criteria		Value	Score
1. Primary Firm Location, Workload and Size (Maximum 10 points)			
a. Proximity of firm to project site	Less than 125 miles	5	
	125 miles to 200 miles	2	
	More than 200 miles	0	
b. Amount of fees awarded by Contracting Authority in previous 24 months	Less than \$1,000,000	2	
	\$1,000,000 to \$2,000,000	1	
	More than \$2,000,000	0	
c. Number of licensed professionals	Less than 10 professionals	1	Max = 3
	10 to 20 professionals	2	
	More than 20 than professionals	3	
2. Primary Firm Qualifications (Maximum 30 points)			
a. Project management lead	Experience / ability of project manager to manage scope / budget / schedule / quality	0 - 10	Max = 20
b. Project design lead	Experience / creativity of project designer to achieve owner's vision and requirements	0 - 20	
c. Technical staff	Experience / ability of technical staff to create fully coordinated construction documents	0 - 0	
d. Construction administration staff	Experience / ability of field representative to identify and solve issues during construction	0 - 0	
3. Key Consultant Qualifications (Maximum 20 points)			
a. Key discipline leads	Experience / ability of key consultants to perform effectively and collaboratively	0 - 15	
b. Proposed EDGE-certified Consultant participation*	One additional point for every 2 percent increase in professional services over the advertised EDGE participation goal	0 - 5	
4. Overall Team Qualifications (Maximum 10 points)			
a. Previous team collaboration	Less than 2 sample projects	1	Max = 3
	2 to 4 sample projects	2	
	More than 4 sample projects	3	
b. LEED** Registered / Certified project experience	Registered projects	1	Max = 2
	Certified projects	2	
c. BIM project experience	Training and knowledge	1	Max = 3
	Direct project experience	3	
d. Team organization	Clarity of responsibility / communication demonstrated by table of organization	0 - 2	
5. Overall Team Experience (Maximum 30 points)			
a. Previous team performance	Past performance as indicated by evaluations and letters of reference	0 - 10	
b. Experience with similar projects / delivery methods	Less than 2 projects	0 - 3	
	2 to 4 projects	4 - 6	
	More than 4 projects	7 - 10	
c. Budget and schedule management	Performance in completing projects within original construction budget and schedule	0 - 5	
d. Knowledge of Ohio Capital Improvements process	Less than 3 projects	0 - 1	
	3 to 6 projects	2 - 3	
	More than 6 projects	4 - 5	
		Subtotal	

* Must be comprised of professional design services consulting firm(s) and NOT the primary firm
 ** Leadership in Energy & Environmental Design administered by the Green Building Certification Institute

Notes:

Evaluator:

Name _____

Signature _____ Date _____

PROJECT NUMBER 95060008

STADIUM PHASE I REPAIRS - UPGRADE

PREPARED FOR
BOWLING GREEN STATE UNIVERSITY
 BOWLING GREEN, OHIO

OFFICE OF DESIGN AND CONSTRUCTION
 UNIVERSITY ARCHITECT
 Barbara Shergalis, AIA

PREPARED BY
OSPORTS
 CLEVELAND, OHIO
 PROJECT ARCHITECT/ENGINEERS



STADIUM -
 PHASE I
 REPAIRS -
 UPGRADE

BGSU
 BOWLING GREEN STATE UNIVERSITY
 BOWLING GREEN, OH
 (419) 372-2531

TAG	ISSUED	DATE
A	SD REVIEW	6-22-15
B	DD REVIEW	8-17-15

Unless otherwise stated in Contract, The Osborn Engineering Company retains copyright ownership. Instruments of Service may only be used for the purpose described in the Contract. The Osborn Engineering Company may grant specific usage rights under license, and/or may transfer copyright ownership assignment in writing. Reproduction, re-use or re-distribution of Instruments of Service is prohibited.

DRAWN BY: TJK
 CHECKED BY: JPK
 CLIENT PROJ. NO.: 95060008
 OSBORN PROJ. NO.: 220150051.000

COVER SHEET

DRAWING NO.
G-001

VICINITY MAP



DRAWING INDEX


ARCHITECTURAL	STRUCTURAL	PLUMBING/MECHANICAL/ELECTRICAL
AD1.01 VISITOR'S LOCKER ROOM DEMOLITION PLAN	S-001 STRUCTURAL GENERAL NOTES	P1.05 PLUMBING MEZZANINE PLAN - SOUTHEAST
A1.01 GROUND PLAN - SOUTHEAST	S-002 STRUCTURAL GENERAL NOTES	P4.01 VISITOR'S LOCKER ROOM PLUMBING PLANS
A1.02 GROUND PLAN - NORTHEAST	SD-101 WEST SEAT DECK DEMOLITION PLAN	PS-01 PLUMBING DETAILS AND SCHEDULES
A1.03 GROUND PLAN - SOUTHWEST	SD-102 EAST SEAT DECK DEMOLITION PLAN	
A1.04 GROUND PLAN - NORTHWEST	S-101 CONCRETE FRAMING PLAN SOUTHEAST	ELECTRICAL
A1.05 ENLARGED VISITOR'S LOCKER ROOM FLOOR & REFLECTED CEILING PLAN	S-102 CONCRETE FRAMING PLAN NORTHEAST	E0.01 ELECTRICAL LEGEND, NOTES, AND SCHEDULES
A1.06 HOME LOCKER ROOM REFLECTED CEILING PLAN - ALT #2	S-103 CONCRETE FRAMING PLAN SOUTHWEST	E0.02 ELECTRICAL SPECIFICATIONS
A1.07 ENLARGED GOLF CENTER FLOOR PLAN - ALT #4	S-104 CONCRETE FRAMING PLAN NORTHWEST	E0.10 ELECTRICAL OVERALL GROUND LEVEL PLAN
A1.08 ENLARGED GOLF CENTER REFLECTED CEILING PLAN - ALT #4	S-110 WEST SEAT CONCRETE DECK REPAIR PLAN	E0.20 ELECTRICAL OVERALL MEZZANINE LEVEL PLAN
A1.09 MEZZANINE REFLECTED CEILING PLAN - SOUTHEAST - ALT #3	S-111 EAST SEAT CONCRETE DECK REPAIR PLAN	ED1.01 VISITOR'S LOCKER ROOM ELECTRICAL DEMOLITION PLAN
A1.10 MEZZANINE REFLECTED CEILING PLAN - NORTHEAST - ALT #3	S-201 RAKER BEAM ELEVATION AND SHIM REPAIR DETAILS	ED1.02 HOME LOCKER ROOM ELECTRICAL DEMOLITION PLAN
A1.11 MEZZANINE REFLECTED CEILING PLAN - SOUTHWEST - ALT #3 & 4	S-501 TYPICAL CONCRETE REPAIR DETAILS	ED1.03 ENLARGED GOLF CENTER ELECTRICAL DEMOLITION PLAN
A1.12 MEZZANINE REFLECTED CEILING PLAN - NORTHWEST - ALT #3 & 4	S-502 CONCRETE REPAIR DETAILS	ED1.04 MEZZANINE ELECTRICAL DEMOLITION PLAN - SOUTHEAST
A1.13 PRESS BOX REFLECTED CEILING AND ROOF PLAN - ALT #5		ED1.05 MEZZANINE ELECTRICAL DEMOLITION PLAN - NORTHEAST
A1.14 ROOF PLAN - SOUTHEAST	MECHANICAL	ED1.06 MEZZANINE ELECTRICAL DEMOLITION PLAN - SOUTHWEST
A1.15 ROOF PLAN - NORTHEAST	MP1.01 HVAC AND PLUMBING LEGENDS, ABBREVIATIONS, AND NOTES	ED1.07 MEZZANINE ELECTRICAL DEMOLITION PLAN - NORTHWEST
A1.16 ROOF PLAN - SOUTHWEST	MD1.01 MECHANICAL GROUND DEMOLITION PLAN - SOUTHEAST	ED1.08 PRESS BOX ELECTRICAL DEMOLITION PLAN
A1.17 ROOF PLAN - NORTHWEST	PO4.01 VISITOR'S LOCKER ROOM PLUMBING DEMOLITION PLANS	E1.01 ENLARGED VISITOR'S LOCKER ROOM ELECTRICAL FLOOR PLANS
A3.01 PARTIAL BUILDING SECTIONS	M1.01 MECHANICAL GROUND PLAN - SOUTHEAST	E1.02 HOME LOCKER ROOM ELECTRICAL PLAN
A3.02 PARTIAL BUILDING SECTIONS	M1.02 MECHANICAL GROUND PLAN - NORTHEAST	E1.03 ENLARGED GOLF CENTER LIGHTING PLAN
A3.03 PARTIAL BUILDING SECTIONS	M1.03 MECHANICAL MEZZANINE PLAN - SOUTHEAST	E1.04 MEZZANINE LIGHTING PLAN - SOUTHWEST
A3.04 PARTIAL BUILDING SECTIONS	M1.04 MECHANICAL MEZZANINE PLAN - NORTHEAST	E1.05 MEZZANINE LIGHTING PLAN - SOUTHEAST
A3.05 PARTIAL BUILDING SECTIONS	M1.05 MECHANICAL MEZZANINE PLAN - SOUTHWEST	E1.06 MEZZANINE LIGHTING PLAN - SOUTHWEST
A4.01 DETAILS	M1.06 MECHANICAL MEZZANINE PLAN - NORTHWEST	E1.07 MEZZANINE LIGHTING PLAN - SOUTHWEST
A4.02 DETAILS		E1.08 PRESS BOX LIGHTING PLAN
A4.03 PRESS BOX & STADIUM CLUB FINISH PLANS - ALT #5	PLUMBING	
A5.04 VISITOR LOCKER ROOM FINISH PLAN & FINISH LEGEND	P1.01 PLUMBING GROUND PLAN - SOUTHEAST	
	P1.02 PLUMBING GROUND PLAN - NORTHEAST	
	P1.03 PLUMBING GROUND PLAN - SOUTHWEST	
	P1.04 PLUMBING GROUND PLAN - NORTHWEST	
	P1.02 PLUMBING MEZZANINE PLAN - SOUTHEAST	

LOCATION MAP



EXAMINED BY	DATE	EXAMINED BY	DATE	EXAMINED BY	DATE	EXAMINED BY	DATE	EXAMINED BY	DATE
DEPARTMENT OF ATHLETICS ATHLETIC DIRECTOR		UNIVERSITY ARCHITECT FACILITIES DESIGN AND CONSTRUCTION							

P:\BGSU\BGSU Campus\20150608_000 Stadium Repairs and Upgrades\DWG\PHASE I\20150608 G-001.dwg
 8/10/2015 3:30 PM Turner, Greg



P:\BGSU\Main Campus\20150501_000 Stadium Repairs And Upgrades\Drawings\A1.01\150501_000_A1.01.dwg
 8/11/2015 9:13 AM
 Robby Aubrey

1 VISITORS LOCKER ROOM DEMOLITION PLAN
 SCALE: 1/4" = 1'-0"



**STADIUM -
 PHASE I
 REPAIRS -
 UPGRADE**

BGSU
 BOWLING GREEN STATE UNIVERSITY
 BOWLING GREEN, OH
 (419)-372-2531

TAG	ISSUED	DATE
A	SD REVIEW	6-22-15
B	DD REVIEW	8-17-15


Unless otherwise stated in Contract, The Osborn Engineering Company retains copyright ownership. Instruments of Service may only be used for the purpose described in the Contract. The Osborn Engineering Company may grant specific usage rights under license, and / or may transfer copyright ownership / assignment in writing. Reproduction, re-use or re-distribution of Instruments of Service is prohibited.

DRAWN BY: ALP
 CHECKED BY: CHK
 CLIENT PROJ. NO.: 95060008
 OSBORN PROJ. NO.: 220150051_000

**VISITOR'S
 LOCKER ROOM
 DEMOLITION
 PLAN**

DRAWING NO.

AD1.01



P:\BGSU\BGSU\Comm\A1.001\001_000 Stadium Repair and Upgrade\Drawings\A1.01\001_000 A1.01.dwg
 8/18/2015 2:39 PM Turner, Greg



**STADIUM -
PHASE I
REPAIRS -
UPGRADE**

BGSU
 BOWLING GREEN STATE UNIVERSITY
 BOWLING GREEN, OH
 (419) 372-2531


TAG	ISSUED	DATE
A	SD REVIEW	6-22-15
B	DD REVIEW	8-17-15

Unless otherwise stated in Contract, The Osborn Engineering Company retains copyright ownership. Instruments of Service may only be used for the purpose described in the Contract. The Osborn Engineering Company may grant specific usage rights under license, and / or may transfer copyright ownership / assignment in writing. Reproduction, re-use or re-distribution of Instruments of Service is prohibited.


DRAWN BY ALP
 CHECKED BY CHK
 CLIENT PROJ. NO. 95060008
 OSBORN PROJ. NO. J20150051.000

**GROUND
PLAN-
SOUTHEAST**

DRAWING NO.
A1.01



P:\BGSU\BGSU\Comm\2011\0001_0001 Stadium Repairs And Upgrades\Drawings\A1.01\0001_0001_01.dwg
 01/10/2015 2:40 PM Turner, Greg



OSPORTS
OSBORN ENGINEERING COMPANY



SCHUMACHER
CONSTRUCTION



CSS Construction
Support & Excellence

STADIUM - PHASE I REPAIRS - UPGRADE

BGSU
BOWLING GREEN STATE UNIVERSITY
 BOWLING GREEN, OH
 (419) 372-2531

TAG	ISSUED	DATE
A	SD REVIEW	6-22-15
B	DD REVIEW	8-17-15


Unless otherwise stated in Contract, The Osborn Engineering Company retains copyright ownership. Instruments of Service may only be used for the purpose described in the Contract. The Osborn Engineering Company may grant specific usage rights under license, and / or may transfer copyright ownership / assignment in writing. Reproduction, re-use or re-distribution of Instruments of Service is prohibited.

DRAWN BY	ALP	
CHECKED BY	CHK	
CLIENT PROJ. NO.	95060008	
OSBORN PROJ. NO.	J20150051.000	

GROUND PLAN-NORTHEAST

DRAWING NO.
A1.02

P:\BGSU\Main Campus\2015\1001_000 Stadium Repair and Upgrade\Drawings\A1.01\1001_000 A1.03.dwg
 8/18/2015 2:43 PM Turner, Greg



**STADIUM -
PHASE I
REPAIRS -
UPGRADE**

BGSU
 BOWLING GREEN STATE UNIVERSITY
 BOWLING GREEN, OH
 (419) 372-2531


TAG	ISSUED	DATE
A	SD REVIEW	6-22-15
B	DD REVIEW	8-17-15

Unless otherwise stated in Contract, The Osborn Engineering Company retains copyright ownership. Instruments of Service may only be used for the purpose described in the Contract. The Osborn Engineering Company may grant specific usage rights under license, and / or may transfer copyright ownership / assignment in writing. Reproduction, re-use or re-distribution of Instruments of Service is prohibited.

DRAWN BY ALP
 CHECKED BY CHK
 CLIENT PROJ. NO. 95060008
 OSBORN PROJ. NO. J20150051.000

**GROUND
PLAN-
SOUTHWEST**

DRAWING NO.
A1.03



P:\BGSU\BGSU\Comm\120115001_000 Stadium Repair and Upgrade\Drawings\A1.07\120115001_000 A1.04.dwg
 8/18/2015 2:45 PM Turner, Greg

1 GROUND LEVEL- NORTHWEST

SCALE: 1/8" = 1'-0"



STADIUM - PHASE I REPAIRS - UPGRADE

BGSU
 Bowling Green State University
 Bowling Green, OH
 (419)-372-2531


TAG	ISSUED	DATE
A	SD REVIEW	6-22-15
B	DD REVIEW	8-17-15

Unless otherwise stated in Contract, The Osborn Engineering Company retains copyright ownership. Instruments of Service may only be used for the purpose described in the Contract. The Osborn Engineering Company may grant specific usage rights under license, and / or may transfer copyright ownership / assignment in writing. Reproduction, re-use or re-distribution of Instruments of Service is prohibited.

DRAWN BY: ALP
 CHECKED BY: CHK
 CLIENT PROJ. NO.: 95060008
 OSBORN PROJ. NO.: J20150051.000

GROUND PLAN- NORTHWEST

DRAWING NO.
A1.04



OSPORTS
 OSBORN ENGINEERING COMPANY
 10000 Highway 100, Suite 100, Bowling Green, OH 43402
 419-372-2531



**STADIUM -
 PHASE I
 REPAIRS -
 UPGRADE**

BGSU
 BOWLING GREEN STATE UNIVERSITY
 BOWLING GREEN, OH
 (419)-372-2531

TAG	ISSUED	DATE
A	SD REVIEW	6-22-15
B	DD REVIEW	8-17-15


Unless otherwise stated in Contract, The Osborn Engineering Company retains copyright ownership. Instruments of Service may only be used for the purpose described in the Contract. The Osborn Engineering Company may grant specific usage rights under license, and / or may transfer copyright ownership / assignment in writing. Reproduction, re-use or re-distribution of Instruments of Service is prohibited.

DRAWN BY: ALP
 CHECKED BY: CHK
 CLIENT PROJ. NO.: 95060008
 OSBORN PROJ. NO.: J20150051.000


**ENLARGED
 VISITOR'S LOCKER
 ROOM FLOOR &
 REFLECTED
 CEILING PLAN**

DRAWING NO.

A1.05




1 ENLARGED VISITOR'S LOCKER ROOM FLOOR PLAN
 SCALE: 1/4" = 1'-0"



2 VISITOR'S LOCKER ROOM REFLECTED CEILING PLAN
 SCALE: 1/4" = 1'-0"

P:\BGSU\Main Campus\2015\0501_000 Stadium Repair And Upgrade\Drawings\A1.05\150501_000_A1_05.dwg
 8/18/2015 2:57 PM Turner, Greg

P:\BGSU\BGSU Campus\2011\0001_000 Stadium Repair and Upgrade\Drawings\Alt#2\20110501 090 A1_06.dwg
 8/18/2011 2:52 PM Turner, Greg



1 ALT #2
 HOME LOCKER ROOM REFLECTED CEILING PLAN
 SCALE: 3/16" = 1'-0"



- KEYNOTES - ALT #2**
- 1 EXISTING SUSPENDED GYP BD CEILING TO REMAIN
 - 2 REMOVE EXISTING ACOUSTIC TILE PANELS AND REPLACE WITH NEW
 - 3 EXISTING GYP BD SOFFIT TO REMAIN. PAINT
 - 4 PATCH AND REPAIR GYP BD SOFFIT TO MATCH EXISTING
 - 5 LINE OF NEW COLLECTOR GUTTER ABOVE



STADIUM - PHASE I REPAIRS - UPGRADE

BGSU
 BOWLING GREEN STATE UNIVERSITY
 BOWLING GREEN, OH
 (419) 372-2531


TAG	ISSUED	DATE
A	SD REVIEW	6-22-15
B	DD REVIEW	8-17-15

Unless otherwise stated in Contract, The Osborn Engineering Company retains copyright ownership. Instruments of Service may only be used for the purpose described in the Contract. The Osborn Engineering Company may grant specific usage rights under license, and / or may transfer copyright ownership / assignment in writing. Reproduction, re-use or re-distribution of Instruments of Service is prohibited.

DRAWN BY: ALP
 CHECKED BY: CHK
 CLIENT PROJ. NO.: 95060008
 OSBORN PROJ. NO.: 220150051.000

HOME LOCKER ROOM REFLECTED CEILING PLAN ALT#2

DRAWING NO.:
A1.06



OSPORTS
OSBORN ENGINEERING COMPANY
10000 State Route 162, Bowling Green, OH 43402
(419) 372-2531



STADIUM -
PHASE I
REPAIRS -
UPGRADE

BGSU
BOWLING GREEN STATE UNIVERSITY
BOWLING GREEN, OH
(419) 372-2531

TAG	ISSUED	DATE
A	SD REVIEW	6-22-15
B	DD REVIEW	8-17-15


Unless otherwise stated in Contract, The Osborn Engineering Company retains copyright ownership. Instruments of Service may only be used for the purpose described in the Contract. The Osborn Engineering Company may grant specific usage rights under license, and / or may transfer copyright ownership / assignment in writing. Reproduction, re-use or re-distribution of Instruments of Service is prohibited.

DRAWN BY ALP
CHECKED BY CHK
CLIENT PROJ. NO. 95060008
OSBORN PROJ. NO. J20150051.000

ENLARGED
GOLF
CENTER
FLOOR PLAN
ALT #4

DRAWING NO.

A1.07




ALT #4
ENLARGED GOLF CENTER FLOOR PLAN

SCALE: 3/16" = 1'-0"




P:\BGSU\Main Campus\2015\0001_000 Stadium Repair and Upgrade\Drawings\A1.07\00010001.dwg
8/18/2015 2:54 PM Turner, Greg

P:\BGSU\BGSU\Comm\120110001_000 Stadium Repair and Upgrade\Drawings\A1.01\120110001_000 A1.01.dwg
 8/18/2015 2:55 PM Turner, Greg



ALT #4
ENLARGED GOLF CENTER REFLECTED CEILING PLAN
 SCALE: 3/16" = 1'-0"

- KEY NOTES: ALT #4**
- 1 REMOVE EXISTING SUSPENDED GYP BD CEILING AND REPLACE WITH NEW 2" ACUSTIC TILE CEILING ASSEMBLY
 - 2 REMOVE EXISTING ACOUSTIC TILE PANELS AND REPLACE WITH NEW
 - 3 PATCH AND REPAIR GYP BD CEILING TO MATCH EXISTING
 - 4 LINE OF NEW COLLECTOR GUTTER ABOVE
 - 5 EXPOSED STRUCTURE, PAINTED



OSPORTS
 CONSULTING ENGINEERS



SCHUMACHER
 ARCHITECTS



CSS Construction
 Support & Excellence

STADIUM - PHASE I REPAIRS - UPGRADE

BGSU
 BOWLING GREEN STATE UNIVERSITY
 BOWLING GREEN, OH
 (419) 372-2531


TAG	ISSUED	DATE
A	SD REVIEW	6-22-15
B	DD REVIEW	8-17-15

Unless otherwise stated in Contract, The Osborn Engineering Company retains copyright ownership. Instruments of Service may only be used for the purpose described in the Contract. The Osborn Engineering Company may grant specific usage rights under license, and / or may transfer copyright ownership / assignment in writing. Reproduction, re-use or re-distribution of Instruments of Service is prohibited.

DRAWN BY: ALP	CHK
CHECKED BY: CHK	
CLIENT PROJ. NO. 95060008	
OSBORN PROJ. NO. J20150051.000	

ENLARGED GOLF CENTER REFLECTED CEILING PLAN
ALT #4
 DRAWING NO. **A1.08**

P:\BGSU\BGSU Campus\20110501_000 Stadium Repair and Upgrades\Drawings\A\20110501_000 A1.00.dwg
 8/18/2011 2:25 PM Turner, Greg



ALT #3
MEZZANINE LEVEL- REFLECTED CEILING PLAN- SOUTHEAST
 SCALE: 1/8" = 1'-0"

- KEY NOTES: ALT #3**
- 1 REMOVE EXISTING 12"x12" CEILING TILES AND REPLACE WITH NEW 2'x2' SUSPENDED ACOUSTICAL TILE CEILING (TYP)
 - 2 NEW GYP BD CEILING
 - 3 NEW CABLE RACEWAY



STADIUM - PHASE I REPAIRS - UPGRADE

BGSU
 BOWLING GREEN STATE UNIVERSITY
 BOWLING GREEN, OH
 (419) 372-2531

TAG	ISSUED	DATE
A	SD REVIEW	6-22-15
B	DD REVIEW	8-17-15


Unless otherwise stated in Contract, The Osborn Engineering Company retains copyright ownership. Instruments of Service may only be used for the purpose described in the Contract. The Osborn Engineering Company may grant specific usage rights under license, and / or may transfer copyright ownership / assignment in writing. Reproduction, re-use or re-distribution of Instruments of Service is prohibited.

DRAWN BY: ALP
 CHECKED BY: CHK
 CLIENT PROJ. NO.: 95060008
 OSBORN PROJ. NO.: 220150051.000

MEZZANINE REFLECTED CEILING PLAN SOUTHEAST ALT #3
 DRAWING NO.

A1.09

P:\BGSU\BGSU\Comm\20110001_0001 Stadium Repair and Upgrade\Drawings\A11.1\20110001_0001_01.dwg
 08/10/2011 2:29 PM Turner, Greg



1 ALT #3
MEZZANINE LEVEL- REFLECTED CEILING PLAN- NORTHEAST
 SCALE: 1/8" = 1'-0"

- KEY NOTES: ALT #3**
- 1 REMOVE EXISTING 12"x12" CEILING TILES AND REPLACE WITH NEW 2'x2' SUSPENDED ACOUSTICAL TILE CEILING (TYP)
 - 2 NEW GYP BD CEILING
 - 3 NEW CABLE RACEWAY



STADIUM - PHASE I REPAIRS - UPGRADE


BGSU
 BOWLING GREEN STATE UNIVERSITY
 BOWLING GREEN, OH
 (419)-372-2531

TAG	ISSUED	DATE
A	SD REVIEW	6-22-15
B	DD REVIEW	8-17-15

Unless otherwise stated in Contract, The Osborn Engineering Company retains copyright ownership. Instruments of Service may only be used for the purpose described in the Contract. The Osborn Engineering Company may grant specific usage rights under license, and / or may transfer copyright ownership / assignment in writing. Reproduction, re-use or re-distribution of Instruments of Service is prohibited.

DRAWN BY: ALP
 CHECKED BY: CHK
 CLIENT PROJ. NO.: 95060008
 OSBORN PROJ. NO.: J20150051.000

MEZZANINE REFLECTED CEILING PLAN NORTHEAST ALT #3
 DRAWING NO. **A1.10**



1 ALT #3 & 4
 MEZZANINE LEVEL- REFLECTED CEILING PLAN- SOUTHWEST
 SCALE: 1/8" = 1'-0"

- KEY NOTES: ALT #3**
- 1 REMOVE EXISTING 12"x12" CEILING TILES AND REPLACE WITH NEW 2"x2" SUSPENDED ACOUSTICAL TILE CEILING (TYP)
 - 2 NEW GYP BD CEILING
 - 3 NEW CABLE RACEWAY



STADIUM - PHASE I REPAIRS - UPGRADE

BGSU
 BOWLING GREEN STATE UNIVERSITY
 BOWLING GREEN, OH
 (419)-372-2531

TAG	ISSUED	DATE
A	SD REVIEW	6-22-15
B	DD REVIEW	8-17-15


Unless otherwise stated in Contract, The Osborn Engineering Company retains copyright ownership. Instruments of Service may only be used for the purpose described in the Contract. The Osborn Engineering Company may grant specific usage rights under license, and / or may transfer copyright ownership / assignment in writing. Reproduction, re-use or re-distribution of Instruments of Service is prohibited.

DRAWN BY: ALP
 CHECKED BY: CHK
 CLIENT PROJ. NO.: 95060008
 OSBORN PROJ. NO.: J20150051.000

MEZZANINE REFLECTED CEILING PLAN SOUTHWEST ALT #3 & 4
 DRAWING NO.

A1.11

P:\BGSU\BGSU\Comm\A\2015\0051.000 Stadium Repair and Upgrade\Drawings\A1.11\A1.11.dwg
 8/18/2015 2:29 PM Turner, Greg



1 ALT #3 & 4
 MEZZANINE LEVEL- REFLECTED CEILING PLAN- NORTHWEST
 SCALE: 1/8" = 1'-0"

- KEY NOTES: ALT #3**
- 1 REMOVE EXISTING 12"x12" CEILING TILES AND REPLACE WITH NEW 2'x2' SUSPENDED ACOUSTICAL TILE CEILING (TYP)
 - 2 NEW GYP BD CEILING
 - 3 NEW CABLE RACEWAY



STADIUM - PHASE I REPAIRS - UPGRADE

BGSU
 BOWLING GREEN STATE UNIVERSITY
 BOWLING GREEN, OH
 (419)-372-2531

TAG	ISSUED	DATE
A	SD REVIEW	6-22-15
B	DD REVIEW	8-17-15


Unless otherwise stated in Contract, The Osborn Engineering Company retains copyright ownership. Instruments of Service may only be used for the purpose described in the Contract. The Osborn Engineering Company may grant specific usage rights under license, and / or may transfer copyright ownership / assignment in writing. Reproduction, re-use or re-distribution of Instruments of Service is prohibited.

DRAWN BY: ALP
 CHECKED BY: CHK
 CLIENT PROJ. NO.: 95060008
 OSBORN PROJ. NO.: 220150051.000

MEZZANINE REFLECTED CEILING PLAN NORTHWEST ALT #3 & 4

DRAWING NO.: A1.12

P:\BGSU\Main Campus\2015\0051_000 Stadium Repair and Upgrade\Drawings\ALT#3\20150051_000 A1.12.dwg
 8/18/2015 3:07 PM Turner, Greg





OSPORTS
OSBORN ENGINEERING COMPANY



SCHUMACHER
ARCHITECTS



CSS Construction
CONSTRUCTION SERVICES

STADIUM - PHASE I REPAIRS - UPGRADE

BGSU
 Bowling Green State University
 Bowling Green, OH
 (419) 372-2531


TAG	ISSUED	DATE
A	SD REVIEW	6-22-15
B	DD REVIEW	8-17-15

Unless otherwise stated in Contract, The Osborn Engineering Company retains copyright ownership. Instruments of Service may only be used for the purpose described in the Contract. The Osborn Engineering Company may grant specific usage rights under license, and/or may transfer copyright ownership assignment in writing. Reproduction, re-use or re-distribution of Instruments of Service is prohibited.

DRAWN BY: ALP
 CHECKED BY: CHK
 CLIENT PROJ. NO.: 95060008
 OSBORN PROJ. NO.: J20150051.000


PRESS BOX REFLECTED CEILING AND ROOF PLAN
ALT #5
 DRAWING NO.: **A1.13**

P:\BGSU\BGSU\Drawings\2015\0051_000 Stadium Repair and Upgrade\BGSU\Drawings\A1.13\A1.13.dwg
 8/18/2015 3:01 PM Turner, Greg



P:\BGSU\BGSU\Comm\1420110001_000 Stadium Repair and Upgrade\Drawings\A11.1\20110501.000 A11.1.dwg
 8/18/2015 3:02 PM Turner, Greg

1 ROOF PLAN- SOUTHEAST
 SCALE: 1/8" = 1'-0"



STADIUM - PHASE I REPAIRS - UPGRADE

BGSU
 BOWLING GREEN STATE UNIVERSITY
 BOWLING GREEN, OH
 (419) 372-2531

TAG	ISSUED	DATE
A	SD REVIEW	6-22-15
B	DD REVIEW	8-17-15


Unless otherwise stated in Contract, The Osborn Engineering Company retains copyright ownership. Instruments of Service may only be used for the purpose described in the Contract. The Osborn Engineering Company may grant specific usage rights under license, and / or may transfer copyright ownership / assignment in writing. Reproduction, re-use or re-distribution of Instruments of Service is prohibited.

DRAWN BY: ALP
 CHECKED BY: CHK
 CLIENT PROJ. NO.: 95060008
 OSBORN PROJ. NO.: 220150051.000

ROOF PLAN- SOUTHEAST

DRAWING NO.: **A1.14**

P:\BGSU\BGSU\Comm\102010001_000 Stadium Repair and Upgrade\Drawings\A1.1\2015051000 A1.1.dwg
 07/10/2015 3:03 PM Turner, Greg



1 ROOF PLAN - NORTHEAST
 SCALE: 1/8" = 1'-0"



**STADIUM -
 PHASE I
 REPAIRS -
 UPGRADE**

BGSU
 BOWLING GREEN STATE UNIVERSITY
 BOWLING GREEN, OH
 (419) 372-2531

TAG	ISSUED	DATE
A	SD REVIEW	6-22-15
B	DD REVIEW	8-17-15


Unless otherwise stated in Contract, The Osborn Engineering Company retains copyright ownership. Instruments of Service may only be used for the purpose described in the Contract. The Osborn Engineering Company may grant specific usage rights under license, and/or may transfer copyright ownership/assignment in writing. Reproduction, re-use or re-distribution of Instruments of Service is prohibited.

DRAWN BY: ALP
 CHECKED BY: CHK
 CLIENT PROJ. NO.: 9506008
 OSBORN PROJ. NO.: 220150051.000

**ROOF PLAN -
 NORTHEAST**

DRAWING NO.
A1.15

P:\BGSU\BGSU\Comm\2015\10001_000 Stadium Repair and Upgrade\Drawings\A1.1\20150510\A1.11.dwg
 07/10/2015 3:04 PM Turner, Greg



1 ROOF PLAN- SOUTHWEST
 SCALE: 1/8" = 1'-0"



STADIUM - PHASE I REPAIRS - UPGRADE

BGSU
 BOWLING GREEN STATE UNIVERSITY
 BOWLING GREEN, OH
 (419)-372-2531

TAG	ISSUED	DATE
A	SD REVIEW	6-22-15
B	DD REVIEW	8-17-15


Unless otherwise stated in Contract, The Osborn Engineering Company retains copyright ownership. Instruments of Service may only be used for the purpose described in the Contract. The Osborn Engineering Company may grant specific usage rights under license, and / or may transfer copyright ownership / assignment in writing. Reproduction, re-use or re-distribution of Instruments of Service is prohibited.

DRAWN BY: ALP
 CHECKED BY: CHK
 CLIENT PROJ. NO.: 9506008
 OSBORN PROJ. NO.: 220150051.000

ROOF PLAN- SOUTHWEST

DRAWING NO.:
A1.16

P:\BGSU\BGSU\Drawings\20110511_001 Stadium Repair and Upgrade\Drawings\A1.1\20110511_001 A1.17.dwg
 8/18/2015 3:05 PM Turner, Greg



1 ROOF PLAN- NORTHWEST
 SCALE: 1/8" = 1'-0"



STADIUM - PHASE I REPAIRS - UPGRADE

BGSU
 BOWLING GREEN STATE UNIVERSITY
 BOWLING GREEN, OH
 (419)-372-2531


TAG	ISSUED	DATE
A	SD REVIEW	6-22-15
B	DD REVIEW	8-17-15

Unless otherwise stated in Contract, The Osborn Engineering Company retains copyright ownership. Instruments of Service may only be used for the purpose described in the Contract. The Osborn Engineering Company may grant specific usage rights under license, and / or may transfer copyright ownership / assignment in writing. Reproduction, re-use or re-distribution of Instruments of Service is prohibited.

DRAWN BY ALP
 CHECKED BY CHK
 CLIENT PROJ. NO. 95060008
 OSBORN PROJ. NO. 220150051.000

ROOF PLAN- NORTHWEST

DRAWING NO.
A1.17



OSPORTS
 CONSULTING ENGINEERS
 1000 Valley Avenue, Suite 100 Bowling Green, OH 43402
 419-372-2531



**STADIUM -
 PHASE I
 REPAIRS -
 UPGRADE**

BGSU
 BOWLING GREEN STATE UNIVERSITY
 BOWLING GREEN, OH
 (419)-372-2531


TAG	ISSUED	DATE
A	SD REVIEW	6-22-15
B	DD REVIEW	8-17-15

Unless otherwise stated in Contract, The Osborn Engineering Company retains copyright ownership. Instruments of Service may only be used for the purpose described in the Contract. The Osborn Engineering Company may grant specific usage rights under license, and / or may transfer copyright ownership / assignment in writing. Reproduction, re-use or re-distribution of Instruments of Service is prohibited.

DRAWN BY: DWN
 CHECKED BY: CHK
 CLIENT PROJ. NO.: 95060008
 OSBORN PROJ. NO.: J20150051.000

**PARTIAL
 BUILDING
 SECTIONS**


DRAWING NO.
A3.01



1 VISITOR'S LOCKER ROOM SECTION
 SCALE: 3/16" = 1'-0"



P:\BGSU\BGSU\Comm\A3\20150051.000 Stadium Repairs and Upgrades\Drawings\A3\20150051.000 A3.01.dwg
 8/18/2015 3:05 PM Turner, Greg



OSPORTS
 CONSTRUCTION MANAGEMENT
 1000 Center Avenue, Suite 100 Bowling Green, OH 43403
 419.372.2531



**STADIUM -
 PHASE I
 REPAIRS -
 UPGRADE**

BGSU
 Bowling Green State University
 Bowling Green, OH
 (419) 372-2531


TAG	ISSUED	DATE
A	SD REVIEW	6-22-15
B	DD REVIEW	8-17-15

Unless otherwise stated in Contract, The Osborn Engineering Company retains copyright ownership. Instruments of Service may only be used for the purpose described in the Contract. The Osborn Engineering Company may grant specific usage rights under license, and / or may transfer copyright ownership / assignment in writing. Reproduction, re-use or re-distribution of Instruments of Service is prohibited.

DRAWN BY: DWN
 CHECKED BY: CHK
 CLIENT PROJ. NO.: 95060008
 OSBORN PROJ. NO.: J20150051.000


**PARTIAL
 BUILDING
 SECTIONS**

DRAWING NO.
A3.02



1 MEZZANINE LEVEL SECTION
 SCALE: 3/16" = 1'-0"
 0 4 8 12

P:\BGSU\Water Campus\2015\0051_000 Stadium Repair and Upgrades\Drawings\A3.02\150501.000 A3.02.dwg
 8/18/2015 3:06 PM Turner, Greg



OSPORTS
OSBORN ENGINEERING COMPANY
10000 State Route 202, Bowling Green, OH 43402
740.372.2531



STADIUM -
PHASE I
REPAIRS -
UPGRADE

BGSU
BOWLING GREEN STATE UNIVERSITY
BOWLING GREEN, OH
(419)-372-2531

TAG	ISSUED	DATE
A	SD REVIEW	6-22-15
B	DD REVIEW	8-17-15


Unless otherwise stated in Contract, The Osborn Engineering Company retains copyright ownership. Instruments of Service may only be used for the purpose described in the Contract. The Osborn Engineering Company may grant specific usage rights under license, and / or may transfer copyright ownership / assignment in writing. Reproduction, re-use or re-distribution of Instruments of Service is prohibited.

DRAWN BY: DWN
CHECKED BY: CHK
CLIENT PROJ. NO.: 95060008
OSBORN PROJ. NO.: J20150051.000

PARTIAL
BUILDING
SECTIONS

DRAWING NO.

A3.03




1 GOLF CENTER SECTION
SCALE: 3/16" = 1'-0"



P:\BGSU\BGSU\Comm\2015\0051_000 Stadium Repair and Upgrade\Drawings\A3\20150051_000 A3.03.dwg
0/10/2015 3:07 PM Turner, Greg

P:\BGSU\Bldg\Comm\20110001_000 Stadium Repair And Upgrades\Drawings\A3.01\20110001_000 A3.04.dwg
0/1/2011 3:09 PM Turner, Greg



**STADIUM -
PHASE I
REPAIRS -
UPGRADE**

BGSU
BOWLING GREEN STATE UNIVERSITY
BOWLING GREEN, OH
(419)-372-2531

TAG	ISSUED	DATE
A	SD REVIEW	6-22-15
B	DD REVIEW	8-17-15

Unless otherwise stated in Contract, The Osborn Engineering Company retains copyright ownership. Instruments of Service may only be used for the purpose described in the Contract. The Osborn Engineering Company may grant specific usage rights under license, and/or may transfer copyright ownership assignment in writing. Reproduction, re-use or re-distribution of Instruments of Service is prohibited.

DRAWN BY: DWN
CHECKED BY: CHK
CLIENT PROJ. NO.: 95060008
OSBORN PROJ. NO.: 20110001_000

**PARTIAL
BUILDING
SECTIONS**

DRAWING NO.
A3.04



**STADIUM -
PHASE I
REPAIRS -
UPGRADE**

BGSU
BOWLING GREEN STATE UNIVERSITY
BOWLING GREEN, OH
(419) 372-2531

TAG	ISSUED	DATE
A	SD REVIEW	6-22-15
B	DD REVIEW	8-17-15


Unless otherwise stated in Contract, The Osborn Engineering Company retains copyright ownership. Instruments of Service may only be used for the purpose described in the Contract. The Osborn Engineering Company may grant specific usage rights under license, and / or may transfer copyright ownership / assignment in writing. Reproduction, re-use or re-distribution of Instruments of Service is prohibited.

DRAWN BY: DWN
CHECKED BY: CHK
CLIENT PROJ. NO.: 95060008
OSBORN PROJ. NO.: J20150051.000

**PARTIAL
BUILDING
SECTIONS**

DRAWING NO.

A3.05



1 GOLF CENTER SECTION

SCALE: 3/16" = 1'-0"



D

C

B

A

P:\BGSU\BGSU\Comm\2015\0501_000 Stadium Repair and Upgrade\Drawings\A3\20150501_000 A3_05.dwg
07/10/2015 3:07 PM Turner, Greg

1


2

3


4

5


6




1 LOCKER CUBBIE
SCALE: 1" = 1'-0"



2 CEILING DETAIL - ALT #3
SCALE: 1" = 1'-0"



3 PRESS BOX CEILING DETAIL ALT #5
SCALE: 1/2" = 1'-0"



4 PRESS BOX CEILING DETAIL ALT #5
SCALE: 1/2" = 1'-0"



**STADIUM -
PHASE I
REPAIRS -
UPGRADE**

BGSU
BOWLING GREEN STATE UNIVERSITY
BOWLING GREEN, OH
(419)-372-2531

TAG	ISSUED	DATE
A	SD REVIEW	6-22-15
B	DD REVIEW	8-17-15

Unless otherwise stated in Contract, The Osborn Engineering Company retains copyright ownership. Instruments of Service may only be used for the purpose described in the Contract. The Osborn Engineering Company may grant specific usage rights under license, and / or may transfer copyright ownership / assignment in writing. Reproduction, re-use or re-distribution of Instruments of Service is prohibited.

DRAWN BY: DWN
CHECKED BY: CHK
CLIENT PROJ. NO.: 95060008
OSBORN PROJ. NO.: J20150051.000


DETAILS

DRAWING NO.
A4.01


P:\BGSU\BGSU\Comp\A4\20150051.000 Stadium Repairs and Upgrades\Drawings\A4\A4.01.Dwg
6/18/2015 3:10 PM Turner, Greg

KEY NOTES: ALT #5

- 1 REMOVE EXIST'G CARPET & INSTALL NEW CARPET
- 2 EXIST'G VAT/VCT TO REMAIN, INSTALL NEW RUBBER TILE FLOORING
- 3 REMOVE EXIST'G VCT & INSTALL NEW RUBBER TILE FLOORING
- 4 EXIST'G CONC SLAB W/ RUBBER TILE FLOORING
- 5 REMOVE EXIST'G CARPET & INSTALL NEW RUBBER STAIR TREADS & RISERS
- 6 PROVIDE & INSTALL SAFETY NOSING ALONG THE LEADING EDGE OF SEATING PLATFORMS & STAIR TREADS
- 7 REMOVE & REINSTALL EXIST'G FIXED SEATING
- 8 INSTALL TUFLEX FLOORING
- 9 INSTALL CERAMIC MOSAIC TILE



ALT #5
 1 PRESS BOX FLOOR FINISH PLAN
 SCALE: 1/8" = 1'-0"



ALT #5
 2 STADIUM CLUB FLOOR FINISH PLAN
 SCALE: 1/8" = 1'-0"



STADIUM -
 PHASE I
 REPAIRS -
 UPGRADE

BGSU
 Bowling Green State University
 Bowling Green, OH
 (419)-372-2531


TAG	ISSUED	DATE

Unless otherwise stated in Contract, The Osborn Engineering Company retains copyright ownership. Instruments of Service may only be used for the purpose described in the Contract. The Osborn Engineering Company may grant specific usage rights under license; and / or may transfer copyright assignment in writing. Reproduction of any part of this drawing without the written consent of Osborn Engineering Company is prohibited.
 OSBORN PROJ. NO. J20150051.000

FINISH PLANS
 ALT #5

DRAWING NO.
 503

J:\BGSU\Projects\USE Interior\Finish\Press And Club\wg
 6/13/2015 1:13 PM
 Administrator



LEGEND OF MATERIALS					
FIN TAG	DESCRIPTION	MFGR	STYLE PATTERN	COLOR	REMARKS
FLOORS					
C1	BROADLOOM CARPET	MOHAWK	BROCATELLE II	COLOR: TBD	12' WIDTH
C2	MODULAR CARPET	MOHAWK	HEXAGONAL INFUSION	COLOR: TBD	12"x36"
RT1	RUBBER TILE	FLEXCO	EVOLVING STYLES WOOD ELEMENTS	COLOR: TBD	SIZE TBD TO BE USED ON STAIR LANDINGS
RT2	RUBBER TILE	FLEXCO	TUFLEX FORCE	COLOR: TBD	27"x27" - 3/8" GAUGE
RT3	RUBBER TILE	FLEXCO	REPEL - SMOOTH	COLOR: TBD	18"x18" - 1/8" GAUGE
CMT	CERAMIC MOSAIC TILE	BALTILE	1"x1" - KEYSTONE	COLOR: TBD	
WALL BASE & ACCESSORIES					
RB1	RUBBER BASE	FLEXCO	TP BASE 2000	COLOR: TBD	4" COVE
ST	STAIR TREAD	FLEXCO	170 SMOOTH RUBBER	COLOR: TBD	2" SAFETY STRIP
SN	STAIR NOSING	JOHNSONITE	VCD-XX	COLOR: TBD	TO BE USED WITH C1
Ceilings					
ACT1	ACOUSTICAL CLG TILE & GRD	ARMSTRONG	DUNE 2'x2' REGULAR	COLOR: WHITE	24"x24" SQUARE LAY-IN, 15/16" GRD PRESS BOX AND STADIUM CLUB
ACT2	ACOUSTICAL CLG TILE & GRD	ARMSTRONG	CERAMAQUARO 605	COLOR: WHITE	24"x24" SQUARE LAY-IN, 15/16" GRD LOCKER ROOM



IMAGE OF C2

- KEY NOTES**
- 1 REMOVE EXIST'G CARPET & INSTALL NEW
 - 2 EXIST'G VAT/VCT TO REMAIN, INSTALL NEW CARPET
 - 3 REMOVE EXIST'G VCT & INSTALL NEW RUBBER TILE FLOORING
 - 4 EXIST'G CONC SLAB, W/ RUBBER TILE FLOORING
 - 5 REMOVE EXIST'G CARPET & INSTALL NEW RUBBER STAIR TREADS & RISERS
 - 6 PROVIDE & INSTALL SAFETY NOSING ALONG THE LEADING EDGE OF SEATING PLATFORMS & STAIR TREADS
 - 7 REMOVE & REINSTALL EXIST'G FIXED SEATING
 - 8 INSTALL TUFLEX FLOORING
 - 9 INSTALL CERAMIC MOSAIC TILE

1 LOCKER_ROOM_FINISH_PLAN
SCALE: 1/4" = 1'-0"





OSPORTS
OSBORN SPORTS +
PROFESSIONAL ARCHITECTURE
1000 STATE AVENUE, SUITE 200, BOWLING GREEN, OHIO 43403
(419) 372-2531



SCHUMACHER
CONSTRUCTION
1000 STATE AVENUE, SUITE 200, BOWLING GREEN, OHIO 43403
(419) 372-2531



CSS Construction
Supporting Excellence

**STADIUM -
PHASE I
REPAIRS -
UPGRADE**

BGSU
BOWLING GREEN STATE UNIVERSITY
BOWLING GREEN, OH
(419)-372-2531

TAG	ISSUED	DATE

Unless otherwise stated in Contract, The Osborn Engineering Company retains copyright ownership. Instruments of Service may only be used for the purpose described in the Contract. The Osborn Engineering Company may grant specific usage rights under license; and / or may transfer copyright ownership by assignment in writing. Reproduction of any part of this drawing without the written consent of Osborn Engineering Company is prohibited. OSBORN PROJ. NO. J20150051.000

**FINISH PLANS
FINISH LEGEND**

DRAWING NO.
504

J:\BGSU\Projects\USE Interior, Fitness Press And Clubbing 8/13/2015 3:37 PM Administrator

BUILDING DESIGN CRITERIA

PER OHIO BASIC BUILDING CODE (98C-2011)

OCCUPANCY CATEGORY:	III
BUILDING USE GROUP:	A5
CONSTRUCTION TYPE:	2B
FLOOR LIVE LOADS:	
ELEVATED SLAB -----	100 PSF
LIVE LOAD REDUCTION -----	N.A.
ROOF LIVE LOAD -----	N.A.
SNOW LOAD:	
GROUND SNOW LOAD, Pg -----	30 PSF
EXPOSURE CATEGORY: -----	N.A.
SNOW EXPOSURE: -----	N.A.
SNOW EXPOSURE FACTOR, Ce: -----	N.A.
THERMAL FACTOR, Ct: -----	N.A.
SNOW IMPROVANCE FACTOR -----	N.A.
FLAT ROOF SNOW LOAD, Pt: -----	N.A.
SNOW DRIFT: -----	N.A.
WIND LOAD:	
BASIC WIND SPEED: -----	50 MPH
EXPOSURE CATEGORY -----	N.A.
ROOF FACTOR -----	N.A.
ADJUSTMENT FACTOR FOR HEIGHT & EXPOSURE -----	N.A.
IMPORTANCE FACTOR -----	N.A.
INTERNAL PRESSURE COEFFICIENT -----	N.A.
WIND PRESSURES -----	N.A.

GENERAL NOTES:

- SEE SPECIFICATIONS FOR QUALITY OF CONSTRUCTION REQUIRED, WORKMANSHIP, MANUFACTURING AND INDUSTRY STANDARDS, PHYSICAL PROPERTIES OF MATERIALS, CONFORMANCE TO CODES AND REGULATIONS, GUARANTEE AND WARRANTY REQUIREMENTS.
- THE CONTRACTOR SHALL VERIFY ALL DIMENSIONS, ELEVATIONS AND CONDITIONS RELATED TO EXISTING CONSTRUCTION, EXISTING SERVICES, AND THE SITE BEFORE BEGINNING WORK.
- CONSTRUCTION LOADS SHALL NOT EXCEED DESIGN LIVE LOADS. THE CONTRACTOR SHALL BE RESPONSIBLE FOR ALL DESIGN AND ANALYSIS REQUIRED TO SUPPORT CONSTRUCTION EQUIPMENT USED IN CONSTRUCTING THIS PROJECT.
- THE CONTRACTOR IS SOLELY RESPONSIBLE FOR THE FOLLOWING ITEMS THAT WILL NOT BE REVIEWED BY THE OWNER, OR ENGINEER.
 - A. DIMENSIONS, ELEVATIONS AND CONDITIONS TO BE CONFIRMED AND CORRELATED AT THE SITE.
 - B. FABRICATION PROCESS INFORMATION.
 - C. MEANS, METHODS, TECHNIQUES, PROCEDURES OF CONSTRUCTION AND CONSTRUCTION SAFETY.
 - D. COORDINATION OF THE WORK OF ALL TRADES.
 - E. QUALITY ASSURANCE SUBMITTALS.
- SEAT DECK WORK, ALSO INCLUDES THE REMOVAL AND REINSTALLATION OF EXISTING SEAT BENCHES AND INDIVIDUAL SEATS.
- REMOVE AND REINSTALL CONDUITS, PIPING, DRAINS, ETC AS NEEDED TO PERFORM CONCRETE AND JOINT REPAIRS.
- CONTRACTOR IS RESPONSIBLE FOR PROTECTION OF HVAC AIR INTAKES, STORM DRAINS, ETC FROM DUST AND DEBRIS.

CAST IN PLACE CONCRETE:

- CAST-IN-PLACE CONCRETE WORK SHALL CONFORM TO ACI 318-11 AND TO THE LATEST ACI STANDARDS IN EFFECT AT BID DATE.
- ULTIMATE COMPRESSIVE STRENGTH OF CONCRETE IN 28 DAYS: 5000 PSI
- REINFORCING BARS: ASTM 615, GRADE 60 (U.L.D.) WELDING OR TACK WELDING A615 BARS SHALL NOT BE PERMITTED.
- REINFORCING BAR LAP SPLICES AND TENSION DEVELOPMENT LENGTHS SHALL CONFORM WITH TABLES SHOWN ON THIS SHEET.
- BEND ALL HORIZONTAL WALL AND BEAM BARS AROUND ALL CORNERS, UNLESS OTHERWISE NOTED.
- REINFORCING BARS REQUIRED FOR PROPER SUPPORT OF PRINCIPAL REINFORCING SHALL BE DETAILED AND SUPPLIED BY THE CONTRACTOR WHETHER OR NOT THEY ARE INDICATED ON THE DRAWINGS. THE MINIMUM BAR SIZE SHALL BE #4 AND THE MAXIMUM BAR SUPPORT SPACING SHALL BE 36" ON CENTER. WELDED WIRE FABRIC SHALL NOT BE USED FOR THE SUPPORT OF PRINCIPAL REINFORCING.
- NO CONCRETE SHALL BE PLACED UNTIL THE PROPOSED CONCRETE MIX AND TEST HAVE BEEN SUBMITTED AND AFTER THE CONTRACTOR HAS RECEIVED WRITTEN ACKNOWLEDGEMENT.
- ALL CEMENT SHALL BE TYPE I OR TYPE II, BLENDED CEMENTS SHALL NOT BE USED.
- CONCRETE SHALL BE DISCHARGED AT THE SITE WITHIN 1 1/2 HOURS AFTER WATER HAS BEEN ADDED TO THE CEMENT AND AGGREGATES. ADDITION OF WATER TO THE MIX AT THE PROJECT SITE WILL NOT BE PERMITTED. ALL WATER MUST BE ADDED AT THE BATCH PLANT. SLUMP MAY BE ADJUSTED ONLY THROUGH THE USE OF ADDITIONAL WATER REDUCING ADMIXTURE OR HIGH RANGE WATER REDUCING ADMIXTURE.
- ALL CONCRETE SHALL CONTAIN A WATER REDUCING ADMIXTURE CONFORMING TO ASTM C494, TYPE A, F OR G.
- CALCIUM CHLORIDE SHALL NOT BE PERMITTED NOR SHALL ANY ADMIXTURE CONTAINING CALCIUM CHLORIDE BE PERMITTED.
- ALL CONCRETE SHALL CONTAIN AN AIR-ENTRAINED ADMIXTURE CONFORMING TO ASTM C260. THE AMOUNT OF ENTRAINED AIR SHALL BE 6% ±1.5%.
- PROVIDE CONSTRUCTION JOINTS IN ACCORDANCE WITH ACI 318 SEC. 6.4.
- 3/4" CHAMFER FOR EXPOSED EDGES OF CONCRETE, UNLESS OTHERWISE NOTED.

REINFORCING BAR CLEARANCE TABLE

LOCATION	CLEARANCE (±1/4")
WALLS EXTERIOR FACE #5 AND SMALLER	1 1/2"
WALLS EXTERIOR FACE #6 AND LARGER	2"
CURBS	1 1/2"
TREADS AND RISERS	1"

REINFORCING LAP LENGTH SCHEDULES
F'c = 5000 P.S.I. NORMAL WEIGHT

BAR SIZE	TOP BAR LENGTH (IN.)						OTHER BAR LENGTH (IN.)					
	CATEGORY						CATEGORY					
	1	2	3	4	5	6	1	2	3	4	5	6
3	16	16	16	16	16	16	16	16	16	16	16	16
4	23	22	22	22	22	22	18	17	17	17	17	17
5	36	29	27	27	27	27	28	22	21	21	21	21
6	51	41	36	33	33	33	39	31	27	25	25	25
7	69	55	48	39	38	38	53	43	37	30	29	29
8	91	73	64	51	46	43	70	56	49	39	35	33
9	115	92	81	65	58	49	89	71	62	50	44	38
10	146	117	102	82	73	59	112	90	79	63	56	45
11	179	143	126	101	90	72	138	110	97	77	69	55

CATEGORY DETERMINATION TABLE FOR SCHEDULES ABOVE				
CONCRETE COVER	CENTER TO CENTER BAR SPACING			STRUCTURAL ELEMENTS
	≤ 3d	> 3d < 4d	≥ 4d < 6d	
< d	1	3	5	LONGITUDINAL BARS IN BEAMS, COLUMNS, INNER LAYER OF WALLS AND SLABS
> d, < 2d	1	3	3	ALL OTHER REINFORCING BARS
> 2d	1	3	5	ALL OTHER REINFORCING BARS

d = NOMINAL BAR DIAMETER.

ZINC RICH GALVANIZED COATING:

- COAT DAMAGED GALVANIZED SURFACES WHERE NOTED WITH A ZINC RICH GALVANIZING PAINT THAT MEETS REQUIREMENTS OF ASTM 780. ACCEPTABLE PRODUCT IS ZRC WORLDWIDE INC. "ZRC GALVITE GALVANIZING REPAIR COMPOUND", OR APPROVED EQUAL.

SEALANT:

- ALL COVE, CONSTRUCTION AND CONTROL JOINT SEALANT SHALL BE "SIKAFLEX-2C NS-10" (OR APPROVED EQUAL). PREPARE SURFACE AND CURE IN ACCORDANCE WITH MANUFACTURER'S REQUIREMENTS.

EXPANSION JOINTS:

- THE BASE BID EXPANSION JOINT SHALL BE MM SYSTEMS EBS EXPANSION JOINT
- ASSUME A TOTAL OF 800 FEET OF EXPANSION JOINT MUST BE REPLACED.

TRAFFIC COATING:

- THE SURFACE AREA TO BE COATED WITH A TRAFFIC COATING ON A-DECK TOTALS APPROXIMATELY 65,000 SF
- THE EXISTING INADEQUATELY BONDED MEMBRANE (TOP COAT AND PRIMER) MUST BE REMOVED FROM ALL SURFACES TO RECEIVE NEW TRAFFIC COATING. THE CONTRACTOR IS SOLELY RESPONSIBLE FOR THE METHODS AND MEANS TO REMOVE THE EXISTING MEMBRANE. EXISTING MEMBRANE MATERIALS THAT RESIST BEING REMOVED MUST UNDERGO A BOND TEST AS NOTED IN SPECIFICATIONS.
- CONTRACTOR SHALL CLEAN AND PREPARE ALL SURFACES TO RECEIVE A TRAFFIC COATING IN ACCORDANCE WITH THE MANUFACTURER'S REQUIREMENTS.
- THE BASE BID TRAFFIC COATING SHALL BE NEGROD SOLVENT-BASE "PEDA-GARD" 40 MIL 5 YEAR JOINT AND SEVERAL WARRANTY SYSTEM.
- CONTRACTOR MUST PROTECT EXISTING SEAT ANCHORS DURING PREPARATION WORK AND ALSO DURING APPLICATION OF TRAFFIC COATING.
- REFER TO THE SPECIFICATIONS FOR ADDITIONAL TRAFFIC COATING INFORMATION.

UNIT PRICE REPAIRS:

- THE FOLLOWING BASE BID REPAIR QUANTITY TABLE INCLUDES THE BASE BID QUANTITIES TO BE USED BY THE CONTRACTOR IN DEVELOPING THEIR BID. THE ACTUAL REPAIR QUANTITIES WILL LIKELY DEVIATE UP OR DOWN FROM THOSE SHOWN BASED ON THE ACTUAL FIELD CONDITIONS. THESE REPAIRS ARE LOCATED IN VARIOUS LOCATIONS THROUGHOUT THE STADIUM. THE CONTRACTOR MUST ASSUME ACCESS RESTRICTIONS THAT MAY EXIST FOR SOME OF THE REPAIR WORK. THEREFORE, THE CONTRACTOR MUST ASSUME THE USE OF HIGH LIFT EQUIPMENT TO ACCESS SELECTED REPAIR AREAS.
- SEE SHEET ??? FOR UNIT PRICE REPAIR TYPE DESCRIPTIONS.

BASE BID REPAIR QUANTITY TABLE

REPAIR DESCRIPTION	REPAIR TYPE	UNIT	BASE BID QUANTITY
OVERHEAD AND VERTICAL PATCHING	A	SF	1,400
HORIZONTAL PATCHING	B	SF	35
NON-STRUCTURAL CRACK REPAIR	C	LF	550
STRUCTURAL CRACK REPAIR	D	LF	215
GUARDRAIL POST REPAIR	E	EA	25
COVE SEALANT REPLACEMENT	F	LF	1,000
CONTROL JOINT REPLACEMENT	G	LF	320
BACKER ROD AND SEALANT REPLACEMENT	H	LF	42,500
STEP REPLACEMENT	I	EA	-
FULL-DEPTH SLAB REPLACEMENT	J	SF	70
FULL-DEPTH WALL REPLACEMENT	K	SF	195
GRINDING OF CONCRETE	L	LF	15
WELD INSTALLATION	M	INL	760
SHIM REPAIR	N	EA	1,835
SHIM ANGLE INSTALLATION	O	EA	60
GUARDRAIL REPLACEMENT	P	LF	70

ALTERNATIVES:

- ALL WORK SHOWN ON THE DRAWINGS IS CONSIDERED AS BASE BID SCOPE UNLESS NOTED AS AN "ALTERNATE".
- BIDDER SHALL PROVIDE A SEPARATE COST IN THEIR BID FOR EACH "ALTERNATE".
- SEE SPECIFICATIONS FOR ADDITIONAL INFORMATION ON "ALTERNATE" ITEMS.
- THE FOLLOWING IS A DESCRIPTION OF THE "ALTERNATE" ITEMS ASSOCIATED WITH THE PROJECT.

ALTERNATE G-1:

- ?????



STADIUM - PHASE I REPAIRS - UPGRADE

BGSU
BOWLING GREEN STATE UNIVERSITY
BOWLING GREEN, OH
(419)-372-2531

TAG	ISSUED	DATE
A	SD REVIEW	6-22-15
B	DD REVIEW	8-17-15

Unless otherwise stated in Contract, The Osborn Engineering Company retains copyright ownership. Instruments of Service may only be used for the purpose described in the Contract. The Osborn Engineering Company may grant specific usage rights under license, and/or may transfer copyright ownership assignment in writing. Reproduction, re-use or re-distribution of Instruments of Service is prohibited.

DRAWN BY: TJK
CHECKED BY: JPK
CLIENT PROJ. NO.: 9506008
OSBORN PROJ. NO.: J20150051.000

STRUCTURAL GENERAL NOTES

DRAWING NO.
S-001

P:\BGSU\BGSU\Comm\2015\0051_000_000 Stadium Repair And Upgrade\2015\0051_000_000_001.dwg
10/20/15 8:00 AM
Kuruman, Tom

STRUCTURAL REPAIR DESCRIPTIONS:

REPAIR TYPE A
OVERHEAD AND VERTICAL PATCHING (SF)
 THIS REPAIR INCLUDES THE PATCHING OF SPALLED, CRACKED OR DELAMINATED CONCRETE ON OVERHEAD OR VERTICAL SURFACES.
 1. SOUND ADJACENT CONCRETE TO IDENTIFY LIMITS OF DETERIORATION.
 2. SHORE THE SURROUNDING AREAS AS NEEDED PRIOR TO BEGINNING THE SAWCUTTING AND DEMOLITION WORK.
 3. REMOVE DETERIORATED CONCRETE WITHOUT DAMAGING EXISTING REINFORCING STEEL.
 4. PREPARE REPAIR AREA IN ACCORDANCE WITH ICRI'S PUBLISHED STANDARD DETAILS ON SHEETS S-501 AND S-502.
 5. PROVIDE STAINLESS STEEL HOOKED DOWELS (PINS) AS A MEANS TO MECHANICALLY ANCHOR THE PATCH MATERIAL TO EXISTING SUBSTRATE UNLESS THE DEPTH OF REPAIR IS AT LEAST 3/4" BELOW DEPTH OF UNDERSIDE OF EXISTING REINFORCING STEEL.
 6. PLACE REPAIR MATERIAL AND CURE IN CONFORMANCE WITH THE MANUFACTURER'S REQUIREMENTS.

REPAIR TYPE B
HORIZONTAL PATCHING (SF)
 THIS REPAIR INCLUDES THE PATCHING OF SPALLED, CRACKED OR DELAMINATED CONCRETE ON HORIZONTAL SURFACES.
 1. SOUND ADJACENT CONCRETE TO IDENTIFY LIMITS OF DETERIORATION.
 2. REMOVE DETERIORATED CONCRETE WITHOUT DAMAGING EXISTING REINFORCING STEEL.
 3. PREPARE REPAIR AREA IN ACCORDANCE WITH ICRI'S PUBLISHED STANDARD DETAILS ON SHEETS S-501 AND S-502.
 4. PROVIDE STAINLESS STEEL HOOKED DOWELS (PINS) AS A MEANS TO MECHANICALLY ANCHOR THE PATCH MATERIAL TO EXISTING SUBSTRATE UNLESS THE DEPTH OF REPAIR IS AT LEAST 3/4" BELOW DEPTH OF UNDERSIDE OF EXISTING REINFORCING STEEL.
 5. PLACE REPAIR MATERIAL AND CURE IN CONFORMANCE WITH THE MANUFACTURER'S REQUIREMENTS.

REPAIR TYPE C
NON-STRUCTURAL CRACK REPAIR (LF)
 THIS REPAIR INCLUDES THE REMOVAL AND REPLACEMENT OF SEALANT IN RANDOM CRACKS AND ALSO CONTROL JOINTS.
 1. COORDINATE WITH THE ENGINEER TO IDENTIFY "NON-STRUCTURAL CRACKS".
 2. DEPENDING ON THE JOINT TYPE: EITHER ROUTE RANDOM CRACK TO THE RECOMMENDED DEPTH/WIDTH OF THE SEALANT MANUFACTURER; OR REMOVE EXISTING SEALANT FROM CONTROL JOINT AND PREPARE SIDES OF JOINT. SEE DETAIL ON SHEET S-502.
 3. PLACE SEALANT IN ACCORDANCE WITH THE MANUFACTURER'S REQUIREMENTS.

REPAIR TYPE D
STRUCTURAL CRACK REPAIR (LF)
 THIS REPAIR INCLUDES THE INSTALLATION OF AN EPOXY GROUT MATERIAL INTO A RANDOM CRACK.
 1. COORDINATE WITH ENGINEER TO IDENTIFY "STRUCTURAL CRACKS".
 2. PREPARE CRACK AND PLACE EPOXY MATERIAL IN ACCORDANCE WITH MANUFACTURER'S REQUIREMENTS.

REPAIR TYPE E
GUARD POST REPAIR (EA)
 THIS REPAIR INCLUDES THE ANCHORING OF THE GUARDRAIL BASE PLATE AT THE BASE OF A GUARDRAIL POST.
 1. REMOVE EXISTING CONCRETE ANCHORS.
 2. EVALUATE AND REMOVE THE BASE PLATE IF DETERIORATED. IF NECESSARY, REPLACE BASE PLATE TO MATCH SIZE AND THICKNESS OF ORIGINAL PLATE; WELD TO EXISTING POST WITH 1/8" FILET WELD.
 3. INSTALL (4) 3/16" STAINLESS STEEL ANCHOR BOLTS WITH A 2" EMBEDMENT.
 4. PREPARE SURFACE OF POST AND APPLY A ZINC-RICH GALVANIZED COAT TO THE AFFECTED AREA OF THE POST.
 5. APPLY EXTERIOR-GRADE PRIMER AND TOP COAT TO ALL EXPOSED AND REPAIRED SURFACES AT THE BASE OF THE POST. COLOR TO MATCH EXISTING.

REPAIR TYPE H
BACKER ROD / SEALANT REPAIR (LF)
 THIS REPAIR INCLUDES THE REMOVAL AND REPLACEMENT OF SEALANT AT THE BASE OF WALLS, HORIZONTAL JOINT IN ALL SEAT DECK RISERS, ETC.
 1. REMOVE EXISTING SEALANT AND BACKER ROD FROM JOINT OPENING.
 2. PLACE BACKER ROD AND SEALANT MATERIAL IN ACCORDANCE WITH THE MANUFACTURER'S REQUIREMENTS.

REPAIR TYPE I
STEP REPLACEMENT (EA)
 THIS REPAIR INCLUDES THE REMOVAL AND REPLACEMENT OF A SEAT DECK AISLE STEP.
 1. REMOVE EXISTING STEP WITHOUT DAMAGING ADJACENT CONCRETE.
 2. PLACE NEW REINFORCING AND CONCRETE IN ACCORDANCE WITH THE DETAIL ON SHEET S-502.

REPAIR TYPE J
FULL DEPTH SLAB REPLACEMENT (SF)
 THIS REPAIR INCLUDES THE REMOVAL AND REPLACEMENT OF UP TO AN 6" THICK ELEVATED SLAB WHERE SHOWN.
 1. SHORE THE SURROUNDING AREAS OF SLAB AS NEEDED PRIOR TO BEGINNING THE SAWCUTTING AND DEMOLITION WORK.
 2. PROTECT EXISTING FINISHES AND CONSTRUCTION BELOW THE REPAIR AREA.
 3. SAWCUT THE PERIMETER OF THE WORK AREA TO A FULL DEPTH TO PREVENT SPALLING OF THE UNDERSIDE SURFACE.
 4. REMOVE DETERIORATED SECTION OF CONCRETE WITHIN SAWCUT PERIMETER WITHOUT DAMAGING ADJACENT SLAB AREAS TO REMAIN.
 5. PLACE SLAB REINFORCING AND CONCRETE IN ACCORDANCE WITH THE DETAIL ON SHEET S-502.
 6. FINISH SURFACE OF NEW CONCRETE TO MATCH ADJACENT FINISH.

REPAIR TYPE K
FULL DEPTH WALL REPLACEMENT (SF)
 THIS REPAIR INCLUDES THE REMOVAL AND REPLACEMENT OF UP TO A 8" THICK CONCRETE WALL WHERE SHOWN.
 1. PROTECT EXISTING FINISHES AND CONSTRUCTION IN THE VICINITY OF THE REPAIR AREA.
 2. SAWCUT THE PERIMETER OF THE WORK AREA TO A DEPTH OF UP TO 1" ON BOTH SIDES OF WALL WITHOUT DAMAGING EXISTING REINFORCING STEEL.
 3. REMOVE DETERIORATED SECTION OF CONCRETE WITHIN THE SAWCUT PERIMETER WITHOUT DAMAGING THE EXISTING REINFORCING STEEL.
 4. PLACE NEW REINFORCING STEEL AND CONCRETE IN ACCORDANCE WITH THE DETAIL ON SHEET S-502.
 5. FINISH THE SURFACE OF NEW CONCRETE TO MATCH ADJACENT FINISH.

REPAIR TYPE L
GRINDING OF CONCRETE (LF)
 THIS REPAIR INCLUDES THE GRINDING OF CONCRETE TO ELIMINATE A TRIP HAZARD.
 1. GRIND SURFACE OF CONCRETE TO ELIMINATE ANY ELEVATION DIFFERENTIAL ACROSS THE JOINT. THE WIDTH OF THE GRINDING MUST EXTEND AWAY FROM THE JOINT TO PROVIDE A MAXIMUM SLOP OF SIX (I.E. A 1/2" VERTICAL OFFSET REQUIRES A GRINDED SURFACE WITH OF 10").

REPAIR TYPE M
WELD INSTALLATION (LF)
 THIS REPAIR INCLUDES THE INSTALLATION OF WELDS AT SHM PLATES LOCATED BELOW THE SEAT DECK RISER BEARING CONNECTION.
 1. SEE NOTE 4 WITHIN THE SHIM PLATE CONNECTION REPAIR PROCEDURE ON SHEET S-201 FOR ADDITIONAL INFORMATION.

REPAIR TYPE N
SHM REPAIR (EA)
 THIS REPAIR INCLUDES RESTORATION OF SHIM PLATE LOCATED BELOW THE SEAT DECK RISER BEARING CONNECTION.
 1. SEE NOTES 1, 2, 3 AND 6 WITHIN THE SHIM PLATE CONNECTION REPAIR PROCEDURE ON SHEET S-201 FOR ADDITIONAL INFORMATION.

REPAIR TYPE O
SHM ANGLE INSTALLATION (EA)
 THIS REPAIR INCLUDES INSTALLATION OF A SUPPLEMENTAL ANGLE LOCATED BELOW THE SEAT DECK RISER BEARING CONNECTION.
 1. SEE NOTE 5 WITHIN THE SHIM PLATE CONNECTION REPAIR PROCEDURE ON SHEET S-201 FOR ADDITIONAL INFORMATION.

REPAIR TYPE P
GUARDRAIL REPLACEMENT (LF)
 THIS REPAIR REPLACEMENT OF THE GUARDRAIL ASSEMBLY WHERE INDICATED ON THE DRAWINGS.
 1. ERECT BARRIERS AND IMPLEMENT OTHER SAFETY MEASURES AS NECESSARY IN THE VICINITY OF THE WORK PRIOR TO COMMENCING REMOVAL OF EXISTING GUARDRAIL ASSEMBLY.
 2. SAWCUT A CLEAN EDGE ON THE GUARDRAIL AT THE LIMIT OF GUARDRAIL SECTION TO BE REPLACED.
 3. REMOVE GUARDRAIL ASSEMBLY INCLUDING BASE PLATE AND CONCRETE ANCHORS.
 4. INSTALL NEW GUARDRAIL ASSEMBLY TO MATCH THE MATERIAL, SIZE, AND APPEARANCE OF THE ADJACENT REMAINING GUARDRAIL SECTIONS. PROVIDE A COUPLING AS NEEDED TO SECURE NEW GUARDRAIL TO EXISTING.
 5. PROVIDE A NEW BASE PLATE TO MATCH SIZE AND THICKNESS OF ORIGINAL PLATE.
 6. INSTALL (4) 3/16" STAINLESS STEEL ANCHOR BOLTS WITH A 2" EMBEDMENT.
 7. APPLY EXTERIOR-GRADE PRIMER AND TOP COAT TO ALL EXPOSED SURFACES OF BOTH NEW GUARDRAIL ASSEMBLY; AND ALSO AREAS OF THE EXISTING GUARDRAIL ASSEMBLY AFFECTED BY THE WORK. COLOR TO MATCH EXISTING.



**STADIUM -
 PHASE I
 REPAIRS -
 UPGRADE**

BGSU
 BOWLING GREEN STATE UNIVERSITY
 BOWLING GREEN, OH
 (419)-372-2531

TAC	ISSUED	DATE
A	SD REVIEW	6-22-15
B	DD REVIEW	8-17-15

Unless otherwise stated in Contract, The Osborn Engineering Company retains copyright ownership. Instruments of Service may only be used for the purposes described in the Contract. The Osborn Engineering Company may grant specific usage rights under license, and / or may transfer copyright ownership / assignment in writing. Reproduction, re-use or re-distribution of Instruments of Service is prohibited.


DRAWN BY: TJK
 CHECKED BY: JPK
 CLIENT PROJ. NO.: 9506008
 OSBORN PROJ. NO.: J2015051.000

**STRUCTURAL
 GENERAL
 NOTES**

DRAWING NO.
S-002

D
 C
 B
 A

P:\BGSU\BGSU\Drawings\2015\0001_0001 Stadium Repairs and Upgrades\2015\0001_0001 S-002.dwg
 8/10/2015 8:07 AM
 kurumaki, Tom



WEST SEAT DECK DEMOLITION PLAN
 SCALE: 1/16" = 1'-0"
 NORTH

DEMOLITION PLAN NOTES:

1. REMOVE EXISTING CHECKERED PLATE COVER AT BOTH EXPANSION JOINTS. RE-INSTALL PLATE AFTER DECK REPAIRS ARE COMPLETED.
2. REMOVE JOINT MATERIALS WITHIN BOTH EXPANSION JOINT OPENINGS FROM ROW 1 THRU UPPER CROSS-AISLE.
3. REMOVE EXISTING RUBBER MEMBRANE AT CONSTRUCTION JOINTS (SEE PLAN).
4. REMOVE EXISTING BACKER ROD AND SEALANT FROM ALL CONSTRUCTION JOINTS FROM ROW 1 UP TO BACK WALL.
5. REMOVE EXISTING BACKER ROD AND SEALANT FROM HORIZONTAL JOINTS ON EVERY RISER.
6. REMOVE, STORE AND REINSTALL ALL SEAT BENCHES AND INDIVIDUAL SEATS. LABEL ITEMS AS NEEDED TO ENSURE THEY ARE REINSTALLED IN THE PROPER LOCATION.

LEGEND:

	SEAT SECTION NUMBER
	EX. TRAFFIC COATING ON TREAD AND RISER
	EX. TRAFFIC COATING ON RISER ONLY
	EX. RUBBER MEMBRANE ON TREAD AND RISER
	EX. RUBBER MEMBRANE ON RISER ONLY
	EX. RUBBER MEMBRANE ON CONSTRUCTION JOINTS



STADIUM - PHASE I REPAIRS - UPGRADE

BGSU
 BOWLING GREEN STATE UNIVERSITY
 BOWLING GREEN, OH
 (419) 372-2531

TAG	ISSUED	DATE
A	SD REVIEW	6-22-15
B	DD REVIEW	8-17-15

Unless otherwise stated in Contract, The Osborn Engineering Company retains copyright ownership. Instruments of Service may only be used for the purpose described in the Contract. The Osborn Engineering Company may grant specific usage rights under license, and / or may transfer copyright ownership / assignment in writing. Reproduction, re-use or re-distribution of Instruments of Service is prohibited.


DRAWN BY: TJK
 CHECKED BY: JPK
 CLIENT PROJ. NO.: 95060008
 OSBORN PROJ. NO.: 220150051.000

WEST SEAT DECK DEMOLITION PLAN

DRAWING NO.: **SD-101**

P:\BGSU\JMK\Comp\2015\0501_000 Stadium Repair And Upgrade\Drawings\SD-101\SD-101.dwg
 8/10/2015 8:10 AM
 kurman, Tom

P:\BGSU\Main Campus\42010001_000 Stadium Repairs And Upgrades\Drawings\Revit\42010001_000 SD-102.dwg
 01/02/2015 8:17 AM
 Kuramin, Tom



A1 EAST SEAT DECK DEMOLITION PLAN
 SCALE: 1/16" = 1'-0"

DEMOLITION PLAN NOTES:

1. REMOVE EXISTING CHECKERED PLATE COVER AT BOTH EXPANSION JOINTS. RE-INSTALL PLATE AFTER DECK REPAIRS ARE COMPLETED.
2. REMOVE JOINT MATERIALS WITHIN BOTH EXPANSION JOINT OPENINGS FROM ROW 1 THRU UPPER CROSS-AISLE.
3. REMOVE EXISTING RUBBER MEMBRANE AT CONSTRUCTION JOINTS (SEE PLAN).
4. REMOVE EXISTING BACKER ROD AND SEALANT FROM ALL CONSTRUCTION JOINTS FROM ROW 1 UP TO BACK WALL.
5. REMOVE EXISTING BACKER ROD AND SEALANT FROM HORIZONTAL JOINTS ON EVERY RISER.
6. REMOVE, STORE AND REINSTALL ALL SEAT BENCHES AND INDIVIDUAL SEAT'S LABEL ITEMS AS NEEDED TO ENSURE THEY ARE REINSTALLED IN THE PROPER LOCATION.

LEGEND:

- XX - SEAT SECTION NUMBER
- - EX. TRAFFIC COATING ON TREAD AND RISER
- - EX. TRAFFIC COATING ON RISER ONLY
- - EX. RUBBER MEMBRANE ON TREAD AND RISER
- - EX. RUBBER MEMBRANE ON RISER ONLY
- - EX. RUBBER MEMBRANE ON CONSTRUCTION JOINTS



OSPORTS
 STADIUM REPAIRS & UPGRADES
 11000 University Avenue, Suite 100, Bowling Green, OH 43402
 419-372-2531



SCHWALBE
 ARCHITECTS



CSS Construction
 Support & Excellence

STADIUM - PHASE I REPAIRS - UPGRADE

BGSU
 BOWLING GREEN STATE UNIVERSITY
 BOWLING GREEN, OH
 (419)-372-2531

TAG	ISSUED	DATE
A	SD REVIEW	6-22-15
B	DD REVIEW	8-17-15


Unless otherwise stated in Contract, The Osborn Engineering Company retains copyright ownership. Instruments of Service may only be used for the purpose described in the Contract. The Osborn Engineering Company may grant specific usage rights under license, and / or may transfer copyright ownership / assignment in writing. Reproduction, re-use or re-distribution of Instruments of Service is prohibited.

DRAWN BY	DWN
CHECKED BY	CHK
CLIENT PROJ. NO.	95060008
OSBORN PROJ. NO.	J20150051.000

EAST SEAT DECK DEMOLITION PLAN

DRAWING NO.

SD-102



OSPORTS
 OSBORN ENGINEERING COMPANY
 1100 Liberty Avenue, Suite 200, Bowling Green, OH 43403
 (419) 372-2531



**STADIUM -
 PHASE I
 REPAIRS -
 UPGRADE**

BGSU
 BOWLING GREEN STATE UNIVERSITY
 BOWLING GREEN, OH
 (419)-372-2531

TAG	ISSUED	DATE
A	SD REVIEW	6-22-15
B	DD REVIEW	8-17-15

Unless otherwise stated in Contract, The Osborn Engineering Company retains copyright ownership. Instruments of Service may only be used for the purpose described in the Contract. The Osborn Engineering Company may grant specific usage rights under license, and / or may transfer copyright ownership / assignment in writing. Reproduction, re-use or re-distribution of Instruments of Service is prohibited.

DRAWN BY: TJK
 CHECKED BY: CHK
 CLIENT PROJ. NO.: 95060008
 OSBORN PROJ. NO.: 220150051.000

**CONCRETE
 FRAMING
 PLAN
 SOUTH EAST**


DRAWING NO.

S-101

LEGEND:

A - REPAIR TYPE

u - REPAIR TYPE ON UNDERSIDE OF SEAT DECK




A1 CONCRETE FRAMING PLAN - SOUTH EAST

SCALE: 1/8" = 1'-0"

P:\BGSU\BGSU\Comm\2015\0051_000 Stadium Repair And Upgrade\Drawings\Rev\220150051_000 S-101.dwg
 8/10/2015 8:07 AM
 kuruman, Tom

P:\BGSU\JAN\Comm\20150051_000 Stadium Repair and Upgrade\Drawings\Rev\20150051_000 S-102.dwg
 8/10/2015 8:07 AM
 Kurman, Tom



LEGEND:
 A - REPAIR TYPE
 Au - REPAIR TYPE ON UNDERSIDE OF SEAT DECK



**STADIUM -
 PHASE I
 REPAIRS -
 UPGRADE**

BGSU
 BOWLING GREEN STATE UNIVERSITY
 BOWLING GREEN, OH
 (419) 372-2531

TAG	ISSUED	DATE
A	SD REVIEW	6-22-15
B	DD REVIEW	8-17-15


Unless otherwise stated in Contract, The Osborn Engineering Company retains copyright ownership. Instruments of Service may only be used for the purpose described in the Contract. The Osborn Engineering Company may grant specific usage rights under license, and / or may transfer copyright ownership / assignment in writing. Reproduction, re-use or re-distribution of Instruments of Service is prohibited.

DRAWN BY: TJK
 CHECKED BY: CHK
 CLIENT PROJ. NO.: 95060008
 OSBORN PROJ. NO.: 220150051.000

**CONCRETE
 FRAMING
 PLAN
 NORTH EAST**

DRAWING NO.:
S-102

P:\BGSU\BGSU\Comm\2010\0001_000 Stadium Repair And Upgrade\Drawings\Struct\201005100001_000 S-103.dwg
 8/10/2010 8:00 AM
 Korum, Tom



A1 CONCRETE FRAMING PLAN - SOUTH WEST
 SCALE: 1/8" = 1'-0"

LEGEND:
 A - REPAIR TYPE
 AU - REPAIR TYPE ON UNDERSIDE OF SEAT DECK



STADIUM - PHASE I REPAIRS - UPGRADE

BGSU
 BOWLING GREEN STATE UNIVERSITY
 BOWLING GREEN, OH
 (419) 372-2531


TAG	ISSUED	DATE
A	SD REVIEW	6-22-15
B	DD REVIEW	8-17-15

Unless otherwise stated in Contract, The Osborn Engineering Company retains copyright ownership. Instruments of Service may only be used for the purpose described in the Contract. The Osborn Engineering Company may grant specific usage rights under license, and / or may transfer copyright ownership / assignment in writing. Reproduction, re-use or re-distribution of Instruments of Service is prohibited.

DRAWN BY: ALP
 CHECKED BY: CHK
 CLIENT PROJ. NO.: 95060008
 OSBORN PROJ. NO.: 220150051.000

CONCRETE FRAMING PLAN SOUTHWEST

DRAWING NO.: **S-103**



OSPORTS
CONSTRUCTION
11000 Center Avenue, Suite 100, Bowling Green, OH 43402
(419) 372-2531



STADIUM -
PHASE I
REPAIRS -
UPGRADE

BGSU
BOWLING GREEN STATE UNIVERSITY
BOWLING GREEN, OH
(419)-372-2531

TAG	ISSUED	DATE
A	SD REVIEW	6-22-15
B	DD REVIEW	8-17-15


Unless otherwise stated in Contract, The Osborn Engineering Company retains copyright ownership. Instruments of Service may only be used for the purpose described in the Contract. The Osborn Engineering Company may grant specific usage rights under license, and / or may transfer copyright ownership / assignment in writing. Reproduction, re-use or re-distribution of Instruments of Service is prohibited.

DRAWN BY: TJK
CHECKED BY: CHK
CLIENT PROJ. NO.: 95060008
OSBORN PROJ. NO.: 220150051.000


CONCRETE
FRAMING-
NORTHWEST

DRAWING NO.

S-104



P:\BGSU\BGSU\Comp\2015\0051_000 Stadium Repair And Upgrade\Drawings\Struct\20150051_000 S-104.dwg
8/10/2015 8:00 AM
Kuruman, Tom




SECTION THROUGH CONCRETE MEMBER

APPLICABLE TO HYDRODEMOLITION, HYDROMILLING, AND PNEUMATIC, HYDRAULIC, AND ELECTRIC BREAKERS

CAUTION! BEFORE STARTING REMOVALS, REVIEW EFFECT OF REMOVALS ON STRUCTURAL INTEGRITY. PROVIDE SHORING OF MEMBER AS NECESSARY. PARTICULAR CARE SHALL BE EXERCISED AT SLAB-BEAM CONNECTIONS TO COLUMNS.

1. REMOVE LOOSE OR DELAMINATED CONCRETE ABOVE OXIDIZED REINFORCING STEEL. ONCE INITIAL REMOVALS ARE MADE, PROCEED WITH THE UNDERCUTTING OF ALL EXPOSED OXIDIZED (CORRODED) BARS. UNDERCUTTING WILL PROVIDE CLEARANCE FOR UNDER BAR CLEANING, FULL BAR CIRCUMFERENCE BONDING TO SURROUNDING CONCRETE, AND WILL SECURE THE PATCH STRUCTURALLY.
2. PROVIDE MINIMUM 3/4" CLEARANCE BETWEEN EXPOSED REBARS AND SURROUNDING CONCRETE OR 1 1/4" LARGER THAN THE LARGEST AGGREGATE IN REPAIR MORTAR, WHICH EVER IS GREATER.
3. CONCRETE REMOVALS SHALL EXTEND ALONG THE BARS TO LOCATIONS ALONG THE BAR FREE OF BOND INHIBITING CORROSION, AND WHERE THE BAR IS WELL BONDED TO SURROUNDING CONCRETE.
4. IF UNOXIDIZED REINFORCING STEEL IS EXPOSED DURING THE UNDERCUTTING PROCESS, CARE SHALL BE TAKEN NOT TO DAMAGE THE BAR'S BOND TO SURROUNDING CONCRETE. IF BOND BETWEEN BAR AND CONCRETE IS BROKEN, UNDERCUTTING OF THE BAR WILL BE REQUIRED.
5. ANY REINFORCEMENT WHICH IS LOOSE SHALL BE SECURED IN PLACE BY TYING TO OTHER SECURED BARS OR BY OTHER APPROVED METHODS.



SECTION THROUGH CONCRETE MEMBER

APPLICABLE TO HYDRODEMOLITION, HYDROMILLING, AND PNEUMATIC, HYDRAULIC, AND ELECTRIC BREAKERS

CAUTION! BEFORE STARTING REMOVALS, REVIEW EFFECT OF REMOVALS ON STRUCTURAL INTEGRITY. PROVIDE SHORING OF MEMBER AS NECESSARY. PARTICULAR CARE SHALL BE EXERCISED AT SLAB-BEAM CONNECTIONS TO COLUMNS.


1. REMOVE DELAMINATED CONCRETE, UNDERCUT REINFORCING STEEL. (REFER TO REINFORCING STEEL UNDERCUTTING GUIDELINE). REMOVAL ADDITIONAL CONCRETE AS REQUIRED TO PROVIDE MINIMUM REQUIRED THICKNESS OF REPAIR MATERIAL.
2. AT EDGE LOCATIONS PROVIDE EITHER METHOD A OR METHOD B RIGHT ANGLE CUTS. AVOID FEATHER EDGES. FOR SHOTCRETE REPAIRS REFER TO ACI 506 EDGE PREPARATION GUIDELINES. PATCH CONFIGURATIONS SHOULD BE KEPT AS SIMPLE AS POSSIBLE. FOR EXAMPLE:



3. AFTER REMOVALS AND EDGE CONDITIONING ARE COMPLETE, REMOVE BOND INHIBITING MATERIALS (DIRT, CONCRETE SLURRY, LOOSELY BONDED AGGREGATES) BY ABRASIVE BLASTING OR HIGH PRESSURE WATERBLASTING WITH OR WITHOUT ABRASIVE. CHECK THE SURFACES AFTER CLEANING TO INSURE THAT SURFACE IS FREE FROM ADDITIONAL LOOSE AGGREGATE, OR THAT ADDITIONAL DELAMINATIONS ARE NOT PRESENT.
4. IF HYDRODEMOLITION IS USED, CEMENT AND PARTICULATE SLURRY MUST BE REMOVED FROM THE PREPARED SURFACES BEFORE SLURRY HARDENS.

TYPICAL EXPOSING AND UNDERCUTTING REINFORCING STEEL DETAIL

NOT TO SCALE
APPLICABLE TO VERTICAL AND OVERHEAD LOCATIONS



IF REBAR HAS LOST MORE THAN 25% OF ITS CROSS SECTION (20% IF 2 OR MORE CONSECUTIVE PARALLEL BARS ARE EFFECTED) CONSULT THE ENGINEER.

IF REPAIRS ARE REQUIRED TO THE REINFORCING STEEL ONE OF THE FOLLOWING REPAIR METHODS SHOULD BE USED.

1. COMPLETE BAR REPLACEMENT ADDITION OF SUPPLEMENTAL BAR OVER AFFECTED SECTION.
2. NEW BAR MAY BE MECHANICALLY SPLICED TO OLD BAR OR PLACED PARALLEL TO AND APPROXIMATELY 3/4" FROM EXISTING BAR.
3. LAP LENGTH SHALL BE DETERMINED IN ACCORDANCE WITH ACI 318, AND STRUCTURAL GENERAL NOTES




REPAIR OF REINFORCING STEEL DUE TO LOSS OF SECTION


NOT TO SCALE

EDGE AND SURFACE CONDITIONING - TYPE I REPAIR

NOT TO SCALE
APPLICABLE TO VERTICAL AND OVERHEAD LOCATIONS



ALL HEAVY OXIDES AND SCALE SHOULD BE REMOVED FROM THE BAR AS NECESSARY TO PROMOTE MAXIMUM BOND OF REPLACEMENT MATERIAL. OIL FREE ABRASIVE BLAST IS THE PREFERRED METHOD. A TIGHTLY BONDED LIGHT OXIDE BUILD-UP ON THE SURFACE MAY RESULT FROM HIGH-PRESSURE WATERBLASTING, WITH OR WITHOUT ABRASIVE. THIS IS USUALLY NOT DETRIMENTAL TO BOND, UNLESS A PROTECTIVE COATING IS BEING APPLIED TO THE BAR SURFACE, IN WHICH CASE THE COATING MANUFACTURER'S RECOMMENDATIONS FOR SURFACE PREPARATION SHOULD BE FOLLOWED.



CLEANING OF REINFORCING STEEL

NOT TO SCALE



STADIUM - PHASE I REPAIRS - UPGRADE

BGSU
BOWLING GREEN STATE UNIVERSITY
BOWLING GREEN, OH
(419)-372-2531

TAG	ISSUED	DATE
A	SD REVIEW	8-22-15
B	DD REVIEW	8-17-15

Unless otherwise stated in Contract, The Osborn Engineering Company retains copyright ownership. Instruments of Service may only be used for the purpose described in the Contract. The Osborn Engineering Company may grant specific usage rights under license, and / or may transfer copyright ownership / assignment in writing. Reproduction, re-use or re-distribution of Instruments of Service is prohibited.

DRAWN BY: DWN
CHECKED BY: CHK
CLIENT PROJ. NO.: 95060008
OSBORN PROJ. NO.: 220150051.000

TYPICAL CONCRETE REPAIR DETAILS

DRAWING NO.
S-501

P:\BGSU\Main Campus\42010001_000 Stadium Repair And Upgrade\Drawings\Revit\42010001_S-501.dwg
8/10/2015 8:07 AM
Kurmin, Tom



STADIUM -
PHASE I
REPAIRS -
UPGRADE

BGSU
BOWLING GREEN STATE UNIVERSITY
BOWLING GREEN, OH
(419)-372-2531


TAG	ISSUED	DATE
A	SD REVIEW	6-22-15
B	DD REVIEW	8-17-15

Unless otherwise stated in Contract, The Osborn Engineering Company retains copyright ownership. Instruments of Service may only be used for the purpose described in the Contract. The Osborn Engineering Company may grant specific usage rights under license, and / or may transfer copyright ownership / assignment in writing. Reproduction, re-use or re-distribution of Instruments of Service is prohibited.


DRAWN BY: DWN
CHECKED BY: CHK
CLIENT PROJ. NO.: 95060008
OSBORN PROJ. NO.: 220150051.000

CONCRETE
REPAIR
DETAILS



DRAWING NO.
S-502



REPAIR TYPE K - FULL DEPTH WALL REPLACEMENT
NOT TO SCALE



REPAIR TYPE J - FULL DEPTH SLAB REPLACEMENT
NOT TO SCALE



REPAIR TYPE C - NON-STRUCTURAL CRACKS
NOT TO SCALE

CAUTION! BEFORE STARTING REMOVALS, REVIEW EFFECT OF REMOVALS ON STRUCTURAL INTEGRITY. PROVIDE SHORING OF MEMBER AS NECESSARY. PARTICULAR CARE SHALL BE EXERCISED AT SLAB/BEAM CONNECTIONS TO COLUMNS.


REPAIR TYPE A & B - REMOVAL GEOMETRY
NOT TO SCALE

REPAIR TYPE I - STEP PLACEMENT
NOT TO SCALE

REPAIR TYPE P - GUARDRAIL REPLACEMENT
NOT TO SCALE

P:\BGSU\Main Campus\220150051.000 Stadium Repair And Upgrade\Drawings\Struct\220150051.000 S-502.dwg
8/10/2015 8:10 AM
Kurmin, Tom

1 2 3 4 5 6



OSPORTS
 OSBORN ENGINEERING COMPANY
 1000 Valley Avenue, Suite 200, Bowling Green, OH 43402
 (419) 372-2531



**STADIUM -
 PHASE I
 REPAIRS -
 UPGRADE**

BGSU
 BOWLING GREEN STATE UNIVERSITY
 BOWLING GREEN, OH
 (419) 372-2531


TAG	ISSUED	DATE
TA	SD REVIEW	6-23-15
BA	DD REVIEW	8-17-15

Unless otherwise stated in Contract, The Osborn Engineering Company retains copyright ownership. Instruments of Service may only be used for the purpose described in the Contract. The Osborn Engineering Company may grant specific usage rights under license, and/or may transfer copyright ownership assignment in writing. Reproduction, re-use or re-distribution of Instruments of Service is prohibited.

DRAWN BY: SPE
 CHECKED BY: BGK
 CLIENT PROJ. NO.: 95060008
 OSBORN PROJ. NO.: 220150051.000

**MECHANICAL
 GROUND
 DEMOLITION
 PLAN -
 SOUTHEAST**
 DRAWING NO.

MD1.01



GENERAL SHEET NOTES

1. CONTRACTOR RESPONSIBLE FOR VERIFYING ALL EXISTING CONDITIONS BEFORE STARTING WORK.

SHEET KEYNOTES

1. REMOVE AND RELOCATE EXISTING EXHAUST BRANCH, INCLUDING GRILLES. CONTRACTOR TO DETERMINE EXACT LIMIT OF DEMOLITION BASED ON FIELD CONDITIONS. REFER TO M-101 FOR NEW WORK.
2. REMOVE AND RELOCATE EXISTING SUPPLY BRANCH, INCLUDING DIFFUSERS. CONTRACTOR TO DETERMINE EXACT LIMIT OF DEMOLITION BASED ON FIELD CONDITIONS. REFER TO M-101 FOR NEW WORK.
3. ETR 146X EXH GRILLE, 300 CFM
4. ETR 106X EXH GRILLE, 40 CFM
5. ETR 12X12 EXH GRILLE, 200 CFM
6. ETR 96X SA DIFFUSER, 200 CFM
7. ETR 64X SA DIFFUSER, 75 CFM
8. ETR 126X SA DIFFUSER, 195 CFM
9. CONTRACTOR TO INSPECT EXISTING DUCTWORK. REMOVE AND REPLACE ANY DAMAGED INSULATION AND DUCTWORK.
10. REMOVE THERMOSTAT AND MAINTAIN FOR RE-INSTALLATION.

1 MECHANICAL GROUND DEMOLITION PLAN - SOUTHEAST

SCALE: 1/8" = 1'-0"



P:\BGSU\BGSU\Campus\220150051.000 Stadium Repairs And Upgrades\220150051.000\MD1.01.dwg
 8/20/2015 2:20 PM
 (Project: Stadium)



BGSU Doyt Perry Stadium, Bowling Green, Ohio/// FACILITY CONDITIONS ASSESSMENT

ARCHITECTURAL 04/11/13



Figure 1- Panoramic View of Doyt Perry Stadium looking Northwest

EXECUTIVE SUMMARY:

ROSSETTI was retained to provide a Facility Conditions Assessment for Bowling Green State University, related specifically to Architectural and Structural areas. The structural review + testing requirements follows the architectural review starting on page 13.

The architectural review concentrated on the following areas;

- Team Facilities and Spectator Facilities Spaces
- Stadium Bowl Seating: Condition and function of the existing seating.
- Accessibility Study: Review the existing Stadium's general accessibility features
- Building Envelope: Condition and function of the existing architectural wall systems.

The objective of the assessment is to evaluate the existing condition and expected remaining service life of the Stadium's systems and infrastructure.

On March 8th, 2013 ROSSETTI made a site visit to observe the existing conditions of the facility. It should be noted that no

testing, instruments or destructive investigation methods were applied; this was an observational evaluation only. We reviewed example rooms of each type within the facility related to the scope of work, performed multiple walks around the exterior of the facility and on roof portions of the Suite and Media areas. The assessment provides recommendations based on the observations. We utilize photographs to help describe the existing conditions as much as possible. The existing Sebo Center Facility was not fully reviewed as part of this assessment as this is the most recent addition to the Stadium.

Generally speaking the facility has issues that could fall into overall categories, short term and future:

Short Term (within 1 year)

- Accessibility issues throughout, including ramped walkway
- Lower Bowl Aisle Railing- We recommend that lower bowl railings be added
- Testing of Precast Riser clip angle connectors- see testing requirements
- Testing of Precast Riser steel end bearing plates- see testing requirements
- Repair Precast Riser spalling concrete
- Prepare Precast for installing traffic coating over full stadia
- Repair of steel beams encased in concrete at upper boxes
- Testing Beam Support Corbel- see testing requirements
- Lower Bowl Seating and Retaining Walls repair/replace
- Remove loose steel decking under walkway ramps
- Grouting of Sport Light pole bases
- Replace slabs within concession stands
- Replace Egress Stair at East side Elevator bridge
- Test all guardrails- see testing requirements
- Replace joint sealant at all wall/ramps intersections
- Clean and seal all exterior cmu walls
- Test Precast Wall panel connection- see testing requirements
- Test Spray Insulation in press box – see testing requirements
- Test/Inspect Roof Membrane to determine repairs
- Implement repair program on Precast Riser clip angle connectors
- Implement repair program on Precast Riser steel end bearing plates
- Implement repair on Beam Support Corbel

- Replace Precast Riser joint sealant throughout
- Repair Concrete Main load bearing frames minor spalling
- Repair Concrete Slabs at top of stadia
- Repair Cracking in Precast panels
- Clean and repair steel stairs at Mezzanine ends
- Repair or Replace all steel guardrails
- Repair cracks in cmu walls and seal
- Replace Sealant in exterior windows/ doors
- Repair Roof leaks or Replace roofing
- MEP systems- Not reviewed but assumed to be near end of service life based on observations
- Seating + Supports

BGSU Doyt Perry Stadium, Bowling Green, Ohio/// FACILITY CONDITIONS ASSESSMENT

ARCHITECTURAL 04/11/13

FACILITY BACKGROUND:

Doyt Perry Stadium is a stadium in Bowling Green, Ohio, United States. It is primarily used for college football, and is the home field of the Bowling Green State University Falcons. The stadium was designed by Osborn-Papesh Architects of Cleveland, Ohio in 1965.

Constructed in 1966 for approximately \$3 million as a replacement for the 43-year-old University Stadium, Doyt Perry Stadium had a capacity of 23,272 until bleacher seats were installed in both end zones in 1982 (those bleachers have since been removed, to give way for the Sebo Athletic Center and Falcon Club Boosters, giving BGSU the 24,000 current capacity).

On October 1, 1966, the stadium opened with a 13-0 win over Dayton. The stadium was named for Doyt L. Perry, a highly successful coach and athletic director at the school. Through 46 seasons, the Bowling Green Falcons have enjoyed an impressive record at Doyt Perry Stadium. Since that time, the Falcons have won over 66 percent of their home games, compiling a 140-68-6 record in the 214 games played at Doyt Perry Stadium.

On Oct. 8, 1983, a huge crowd of 33,527 packed into Perry Stadium for the annual Northwest Ohio rivalry between Bowling Green and Toledo, establishing a school and MAC record for single-game attendance. The Falcons went on to set a season record, breaking the six-digit figure for five games with a total draw of 100,021. It marked the first time in history that Bowling Green averaged more than 20,000 fans for five home football games.

That figure was topped in 1985, when Bowling Green posted a perfect record (11-0) in the regular season and clinched the MAC Championship by shutting out Toledo at Perry Stadium in November. More than 28,000 fans turned out that day, raising Bowling Green's season attendance to an average of 22,422.

In 1994, BG fans bettered the mark of 1985 as 114,802 fans, an average of 22,960, attended the five home games.

The construction of elevators on both sides of the stadium, completed in early 1998, has made the stadium more accessible for all fans.

In 2001 permanent lighting was installed at the venue.

In 2003, Falcon faithful attended sellout games against Northern Illinois and Toledo as ESPN broadcasted three games live from the facility and brought its weekly college football show, Gameday, to Bowling Green. That year, BGSU averaged more than 21,000 per home game.

For the 2007 football season the stadium received an upgrade. The Sebo Athletic Center encloses the North endzone and houses the band seating, luxury suites, offices, training facilities and new box offices. The traditional grass field was also replaced with a Field Turf artificial surface.

The stadium consists of two bowed sideline grandstands. Over the years the stadium also featured steel grandstands at the north and south ends.

Doyt Perry Stadium is more than just a football facility. The east side of the stadium includes locker rooms, equipment and training rooms, along with the Athletic Department offices. The west side is the home of the BGSU Golf Training Center, filled with a 1,200 square foot putting green, locker rooms and hitting bays.

Sitting atop the press box on the west side of the stadium is the plush Stadium Club. The Stadium Club's 106 theatre-type seats provide loyal BGSU fans with the best view of the game. The President's Box, located at the top of the east side of the stadium, provides luxury seating for the University President and guests, along with other supporters of Falcon football.

BGSU Doyt Perry Stadium, Bowling Green, Ohio/// FACILITY CONDITIONS ASSESSMENT

ARCHITECTURAL 04/11/13

ARCHITECTURAL REVIEW:

The Stadium has four primary levels:

- Event/Concourse Level on which the playing field, team locker rooms, operations support spaces, public toilet rooms and concessions are located
- Mezzanine Level (partial on West + East sides)
- Suite Level (East side)
- PressBox Level (West side)
- Stadium Club Level (West side)
- Seating Bowl is made of separate concrete seating sections on the West and East sides
- The Sebo Center located at the North end was not included in this review

EVENT LEVEL: PUBLIC AREAS

TICKET BUILDINGS: There are (4) existing Ticket Buildings that are located outside the facility, they are located on the West and East sides (refer to figure 2).



Figure 2- Ticket Buildings

PUBLIC SIDEWALKS AND PAVING AROUND STADIUM: The existing pavement around the stadium for the concourse appeared generally in good condition on all sides around the facility where the public would have access. While previous

replacement and patching of the pavement was visible and evident, the new pavement appeared flush and even with the existing material and posed no immediate hazard to spectators.

PUBLIC CONCOURSE: The exterior paving is effectively the public concourse. The paving was in good condition, no major holes, cracks or steps that would create any on-going issues.

PUBLIC RAMPED WALKWAYS: The seating bowl is primarily accessed from (8) large ramped walkways, with a distinctive "Y" shaped entry into the seating bowl (refer to figure 3). These ramps are at a slope of 1" rise over 10" of run, as indicated on the original drawings, but they contain no landings, it is one constant slope for approx. 9 feet of vertical rise. The slope and the arrangement do not comply with current building and accessibility codes, which would require a maximum slope of 1" rise over 12" of run and a landing for every 30" of rise. In the case of this location, you would be required to provide (4) 5'-0" long level landings and revise the slope of the ramp. This would add almost 40 feet to the overall length of these ramps at each location. Handrails would also be required on each side to comply with the current building codes (refer to figure 4).



Figure 3- View of Ramped Walkway to Seating Bowl



Figure 4- View of Ramped Walkway with Hand Rails

The construction on the top surface appears to be in acceptable condition. There are noticeable chalking and weathering issues with the CMU walls along the sides, but the walking surface has no visible issues.



Figure 5- View of Underside of Ramped Walkway

BGSU Doyt Perry Stadium, Bowling Green, Ohio/// FACILITY CONDITIONS ASSESSMENT

ARCHITECTURAL 04/11/13

However, the construction on the bottom side of these ramps is another issue (refer to figure 5). It was evident that the supporting metal deck has serious signs of deterioration and appears to be a safety issue for anyone accessing this space. Per the structural assessment, this is not specifically a structural concern, since this decking was used as a form for the ramp.

CONCESSION STANDS: The existing facility contains (8) freestanding concession stands with canopies located at the base of the ramped walkways (refer to figures 6 and 7). It is unclear how many point of sales (POS) machines are setup for each location, but 2-4 POS per stand seems reasonable. This would mean a total amount of 32 POS, which equates to approx. 1 POS for every 718 spectators. This is a very high ratio for a current college facility. We would recommend that the ratio should be closer to 1:200, which would mean a total amount of 115 POS, or an increase of around 83 POS. The public counter height is 3'-6" and would need to have a lowered portion at 3'-0" max. to comply with the current accessibility codes.



Figure 6- Interior of Concession Stand



Figure 7- View of Concession Stand

PUBLIC TOILETS: The existing facility contains a total of (4) Men's and (4) Women's Toilet Rooms. Generally these spaces were in good condition. The painted, floor mounted toilet partitions were in good condition and the ones tested appeared stable and structurally sound. A few locations showed signs of attempts to provide wheelchair accessible stalls, although it was observed that these did not appear to fully comply. These rooms also lacked the required ambulatory stalls and many of the toilet accessories were mounted higher than allowed (refer to figures 8 and 9). The rooms themselves had more than adequate turning clearances, however the existing entry and exit doorways do not. The quantity of existing toilets is well below the current code requirements and would need to be resolved in any future renovation.



Figure 8- Public Toilets- Toilets + Urinals



Figure 9- Public Toilets- Lavs

WAYFINDING SIGNAGE: Simple and clean wayfinding signage helps spectators navigate a facility. Very little wayfinding signage was visible. We did observe some painted letters at the entry to the ramped walkways. We would suggest this signage be

BGSU Doyt Perry Stadium, Bowling Green, Ohio/// FACILITY CONDITIONS ASSESSMENT

ARCHITECTURAL 04/11/13

provided and possibly redesigned at least every ten years to keep the facility current.

BUILDING LIGHTING: The site visit was conducted during the day and as such we were not able to determine if the building/site lighting was adequate or not. Based on observations of the lighting locations, we have no reason to believe there are problems with the lighting.

FOOTBALL FIELD:

FIELD TURF: The traditional grass field was replaced with Field Turf in 2007. The condition of the Field Turf appears to be in good condition. There were no visible defects or issues with the turf (refer to figure 10).



Figure 10- South End Zone looking North across Field Turf field

FIELD LIGHTING: The field lighting is provided from (4) Musco lightpoles. The site visit was conducted during a non-event time and as such we were not able to determine if the field lighting was adequate or not. Based on observations of the lighting quantity and locations, we have no reason to believe there are problems with field lighting (refer to figure 11).



Figure 11- View of Field Lighting, 4 poles

SCOREBOARD: Located at the South end of the field is the main video scoreboard for the facility. The scoreboard was built by Daktronics, originally installed in 2004, was upgraded for the 2012 season has a 15 mm pixel pitch-spacing, and approx. 19' x 35' dimensions. The size of this board is on the smaller size for NCAA Division I football (refer to figure 12).



Figure 12- BGSU Video Scoreboard

EVENT LEVEL: TEAM AREAS

VISITING TEAM LOCKER ROOM: The Visiting Team locker room is located in the SE corner of the facility. The room is very dated and simple, but it does appear to have enough space for the intended use. We assume this room is used for all visiting teams (Football, Track, Soccer, etc...). We did not observe separate training facilities for the Visiting Teams, and all areas including the toilet and shower areas appear to be non-compliant with accessibility guidelines (refer to figure 13).

BGSU Doyt Perry Stadium, Bowling Green, Ohio/// FACILITY CONDITIONS ASSESSMENT

ARCHITECTURAL 04/11/13



Figure 13- View of Visiting Team Lockers

FALCON'S TEAM LOCKER ROOMS (Track/Cross Country, and Men's Soccer): The various BGSU teams noted above located within the facility are generally dated and in need of revisions (refer to figures 14 and 15).



Figure 14- View of BGSU Men's Soccer Lockers



Figure 15- View of BGSU Track/Cross Country Lockers

FALCON ATHLETIC EQUIPMENT ROOM: The Athletic Equipment Storage room appears to be well organized and able to support the intended uses. The addition of more space would allow for a higher capacity storage system (refer to figure 16).



Figure 16- View of Athletic Equipment Storage Room

PLAYER'S LOUNGE: The Player's Lounge appears to be very small in size for the number of athletes it should serve. The current layout appears to have four activities, but it would be difficult to accommodate the number of people needed. The room is also dividable into three smaller spaces for multiple meetings. We would recommend that this room be increased in size to allow for more comfort and relaxation for the athletes (refer to figure 17).



Figure 17- View of Player's Lounge

FALCON FOOTBALL COACHES LOCKER ROOM- The Coach's locker room is located directly adjacent to the Football Locker room. The room contains separate toilet and shower areas, is in good condition and appears adequate.

FALCON FOOTBALL TEAM LOCKER ROOM: The Falcons Football Locker Room was recently renovated in 2007 as part of the Sebo Center project. The room appears larger and more spacious than the other locker rooms, with detailed wood lockers. The space appears very modern and comparable to other current major NCAA locker rooms with nicely done signage and graphics (refer to figures 18 and 19).

BGSU Doyt Perry Stadium, Bowling Green, Ohio/// FACILITY CONDITIONS ASSESSMENT

ARCHITECTURAL 04/11/13



Figure 18- View of Football Locker Room



Figure 19- View of Football Locker Room cont'd

FALCONS TRAINING ROOM (located in the Sebo Center): The Training Room for the Falcon's is part of the Sebo Center and was constructed in 2007. This room is for all of the various sports located in the facility. The room generally appears

a dequate for the intended use including treatment and taping tables, and multiple hydro tubs for therapy (refer to figure 20).



Figure 20- View of Sebo Training Room

WEIGHT ROOM (located in the Sebo Center): The Weight Room for all associated BGSU sports is located in the Sebo Center and was also constructed in 2007. The room seems well equipped and in good condition. The issue is that the room is primarily used by the football team and the other sports have limited access for using this space. It would be recommended to either increase the size of the room or to provide a separate room for the other sports to utilize (refer to figure 21).



Figure 21- View of Sebo Weight Room

FALCON GOLF TRAINING CENTER: The west side of the facility is dominated by the home of the BGSU Golf Training Center, filled with a 1,200 square foot putting green, locker rooms and hitting bays. The complex was created within the (4) original handball courts. This complex appears to be a very unique feature that is available to the BGSU golf teams (refer to figure 22 thru 24). The associated locker rooms however, are very small and dated and could have some renovations to improve them but the golf training complex appears in good condition. Within the center, the Men's Cross Country team also appears to have their lockers located, we would recommend in a renovation, that these lockers be relocated.

BGSU Doyt Perry Stadium, Bowling Green, Ohio/// FACILITY CONDITIONS ASSESSMENT

ARCHITECTURAL 04/11/13



Figure 22- View of Falcon Golf Training Center



Figure 24- View of Putting Green




Figure 25- View of East Corridor Steps



Figure 23- View of Driving Range

BOH CORRIDORS: The backs of house corridors along this level were simple and clean and well lit.

MEZZANINE LEVEL

OFFICE CORRIDOR: The East side Mezzanine Level runs under the full length of the seating. It contains various athletic and coaches offices and some associated conference, storage and related mechanical rooms. The enclosed portions like toilets and conference rooms on the North side have been constructed with a sub-roof system under the precast stadia. Many of these areas show signs of previous water damage over the years. The East office hallway is clean and well lit. Besides the water intrusion issue, the major item of note was the non-accessible hallway with the stairs located at each of the ramped walkways (2 locations within corridor). Actually, although a few offices on this level actually comply with the ADA due to the addition of the elevator in 1995, none of the toilet rooms do. This area would need to be resolved in any proposed renovation (refer to figure 25).

The west side Mezzanine Level is much smaller due to the Golf Training Center. The West side is actually two, smaller un-connected buildings without elevator access. The buildings also contain a variety of athletic and coach offices. The portion at the North end also includes the Softball Locker Room. Again, these areas would be required to comply with accessible guidelines if a renovation occurs.

EGRESS STAIR TOWERS: The Mezzanine Levels on both sides of the facility have some interior and exterior egress stairways. Generally these stairs are in need of repair and re-painting to extend their life. The existing steel stairways from the Mezzanine floor and the Elevator access bridge all appear in various states of deterioration. The worst location is the egress stair on the South side of the stadium from the Elevator bridge. This stair is in immediate need or repair, due to the amount of rusting that is visible. This stair should not be used for fear of injuring visitors or spectators.

BGSU Doyt Perry Stadium, Bowling Green, Ohio/// FACILITY CONDITIONS ASSESSMENT

ARCHITECTURAL 04/11/13



Figure 26- East Side Elevator Bridge Exit Stair- Corroded Steel

MEZZANINE EXTERIOR WALLS/ WINDOWS:

The Mezzanine Level is enclosed with CMU walls and have small windows for each office area. These offices have separate mechanical units mounted under the windows with an attached louver. Based on the existing drawings, it is not clear if any coating or sealer was installed over the exterior surface. The exterior wall is showing signs of water intrusion, noticeable from the visible staining seen on the walls (refer to figure 27). We would recommend the walls be cleaned and an appropriate sealer or coating be applied to limit water from entering the wall system. The construction of the Mezzanine also has an overhang condition that has the floor slab exposed to the exterior, we would suggest an insulated soffit be constructed to provide a more complete envelope.



Figure 27- Mezzanine Exterior Wall- Staining

The windows appear to be original to the facility and are 3/16" gray tinted single pane units per the drawings. These units should be replaced with insulated glass and associated sealant in order to extend the life of the facility. The insulation of the walls and roof should be increased as well.

SUITE/MEDIA LEVEL:

SELECT SEATS/SUITES (EAST SIDE): Along the East Side of the grandstands, there are (8) Suites and (1) President's Suite contained in a single story structure, it is accessed from the elevator and thru the seating bowl (refer to figure 28). The Suites contain two rows of seating with sloped glass toward the field. The sizes of the suites are very small in comparison to other football facilities. They are dated and lack space to provide much beyond the seats viewing the event. We would recommend a Suite Renovation to start within the next 3-5 years that would create a fresh new look for the Suites and associated spaces. The glass facing the field contains large vertical mullions that block some of the view (refer to figures 29 and 30). The President's Suite, with the associated Lounge area behind, seems appropriate for its use.



Figure 28- View of East Side Select Seats/ Suites



Figure 29- View from the President's Suite @ 50 Yard Line

BGSU Doyt Perry Stadium, Bowling Green, Ohio/// FACILITY CONDITIONS ASSESSMENT

ARCHITECTURAL 04/11/13



Figure 30- View from North East Corner of Level

ROOFING: The single ply roofing above the Suite and Pressbox Levels appears generally in good condition. There are some minor areas that felt spongy when walking over, we would suggest a more formal review of the roofing from the manufacturer to determine the remaining life of the current roofing, we would estimate at least 5-8 years with some minor repairs (refer to figure 31).



Figure 31- View of Roof above PressBox

PAGE 11

PRESSBOX (WEST SIDE): The Pressbox Level was similar to the Suite Level on the opposite side except that it includes a second story (refer to figure 32). The spaces in general appeared to be very tight. Some of the spaces on the North side have been revised to Suites. There was a lot of space allowed for Visiting Teams including; Coaches, Radio and Athletic Director. The area allocated for the Working Press seems adequate. The use of the Dark Rooms was not clear today, it would seem possible for these rooms to be re-purposed in a renovation.



Figure 32- View of West Side PressBox

The finishes and overall design of the space feels dated. Most of the amenities seem to be provided, it is just a very compact design without much overflow space. Like the Suites, the egress from this space is out into the seating bowl and down the grandstands. There is no dedicated egress stair towers from these levels.

STADIUM CLUB LEVEL:

STADIUM CLUB: Situated atop the Pressbox on the West side of the stadium is the plush Stadium Club. The Stadium Club's 106 theatre-type seats provide loyal BGSU fans with the best view of the game (refer to figure 33). The access to the Club is either from the West side elevator up to this level or access to the Pressbox and then up a dedicated stair. Associated with this interior portion, there are two exterior roof decks that are used for more spectators to view the game. There is only a single means

of egress from this level, two should be provided to comply with the Building Code.



Figure 33- Stadium Club

VERTICAL CIRCULATION:

PASSENGER ELEVATORS- As noted, two elevators were added in 1998. One elevator is provided for each side. The one on the West side stops at the Pressbox and the Stadium Club. The one on the East side stops at the Mezzanine Level and the Suite Level. The elevators were not used during the site tour but appeared to be typical passenger elevators and were well maintained.

SEATING BOWL:

GENERAL ADMISSION BENCH SEATING:

The main seating bowl consists of aluminum bench seating. This seating allows for approx. 18" of width per person. This is fairly tight by stadium standards today (refer to figure 34).

BGSU Doyt Perry Stadium, Bowling Green, Ohio/// FACILITY CONDITIONS ASSESSMENT

ARCHITECTURAL 04/11/13



Figure 34- View of General Admission Bench Seating

CHAIR BOX SEATING: Along both sides of the grandstands there are sections containing (6) rows of chairback "Box" seating. Also, the West side grandstand, within the middle seating sections there are also individual seat modules mounted to the existing aluminum benches (refer to figure 35).




Figure 35- View of Box Seats

ACCESSIBLE SEATING PLATFORMS: In recent years accessible seating platforms have been installed over three existing rows (refer to figure 36). This occurs within the stadium at (4) locations on each side. These platforms appear to provide capacity for roughly 4 wheelchair and 4 companion seats. This would mean the facility has roughly 32 wheelchair and 32 companion total locations. This is less than what is required in the 2010 ADA Guidelines. Per these guidelines, 126 wheelchair and 126 companion seating is required. Also when the elevators were added to the facility, vertical dispersion should likely have been provided as well, this would allow for seating locations at the top of the bowl as well on both sides.



Figure 36- View of Accessible Seating Platform

STADIA: The precast stadia appears to have no coating over most of the seating bowl. There are a number of locations that have a traffic coating applied over occupied areas. This coating appears to have been repaired multiple times over the years, as the water damage underneath is visible. We would recommend a heavy duty coating be applied over all surfaces to help protect the concrete. There are areas of the precast that have been damaged by water penetration and require repair (refer to figure 37). The seating bowl does not have a center aisle railing which has improved safety results and is required by the Building Code. We would recommend adding this missing aisle railing to improve usability to an aging population.



Figure 37- View of Stepped Aisle

RAILING: The painted steel railing installed throughout the facility appears to be non-galvanized steel. The railings show signs of rust and deterioration and should be evaluated for compliance with Building Codes.

SEATING JOINT SEALANT: The sealant installed within the seating bowl is in various states of decline, as part of any major renovation, the sealant should be removed and replaced complete (refer to figure 38).

BGSU Doyt Perry Stadium, Bowling Green, Ohio/// FACILITY CONDITIONS ASSESSMENT

ARCHITECTURAL 04/11/13



Figure 38- View of Seating Bowl Sealant/ Joint

FIELD ACCESS STAIRS/ EGRESS TO FIELD: The seating bowl relies on egress into the field in the event of emergency to accommodate all the spectators. These stairs (7) locations per side do not provide the required railings. These railings should be provided (refer to figure 39).




Figure 39- Field Access Stairs

TRAFFIC COATING/ WATERPROOFING: Various methods of waterproofing and traffic coatings have been installed over the occupied areas. In some areas, a membrane has been installed, but it is obvious that water has gotten under the membrane and is trapped between the concrete. This membrane has now delaminated from the concrete. We would recommend that this membrane be removed and the traffic coating be reviewed at all locations (refer to figure 40).



Figure 40- View of Delaminated Membrane

BGSU Doyt Perry Stadium, Bowling Green, Ohio/// FACILITY CONDITIONS ASSESSMENT

STRUCTURAL 04/11/13

STRUCTURAL REVIEW

BACKGROUND:

Desai/Nasr Consulting Engineers, as part of the ROSSETTI Team were authorized to perform a Phase I Condition Assessment of the Structural Components for the existing Doyt Perry Stadium Facility located at Bowling Green State University (BGSU), Bowling Green, OH.

A walk-through of the captioned property was conducted on Friday March 8th, 2013. The walk-through was conducted by the following individuals:

Mr. Marc Steinhobel, P.E., SECB – Desai/Nasr Consulting Engineers, Inc.
Mr. Greg Sweeney, AIA, LEED AP - ROSSETTI
Mr. Sunghoon Jung, LEED AP BD+C - ROSSETTI

The purpose of the walk-through was to assess the general conditions of the premises. The walk-through inspection was limited to observations of elements that are readily accessible and visible. For many building types, this means that portions of the structure could not be observed because they are concealed by finishes. All reasonably accessible structural components, such as structure above "lay-in" type ceilings were observed.

No destructive or non-destructive testing was performed at this stage. As such, although it is useful for detecting gross issues, it may not detect every issue, especially subtle or hidden conditions.

Environmental issues, such as mold, asbestos, or any other hazardous material are not covered in the Structural Phase I Condition Assessment.

GENERAL BUILDING DESCRIPTION:

The Doyt Perry Stadium was designed by Osborn-Papesh Architects-Engineers in the mid 1960's. The available set of construction documents is dated July 1965.

Per the original drawings, the building is founded on conventional pad foundations bearing on soils with an allowable bearing pressure of 6,000psf at 5ft below grade and 4,000psf at 3ft below grade. The drawings show the foundation typically bear at 4ft to 5ft below the finished grade elevations and extend below the required frost depth.



Figure 41- View of Stadium from West Side

The east and west precast stadium seating is supported by 19 cast-in-place concrete frames that play outwards from a central axis located at centerfield.

The lowest level of seating is constructed with cast-in-place concrete steps on grade bounded by cast-in-place concrete retaining walls on all sides. The high-end retaining wall forms one side of the corridor that runs the length of the stadium on each side.

The remaining stepped seating is constructed with precast-Tee risers that bear on embedded steel plates cast into the supporting frames. The individual steps are tied together with clip angles that are mechanically fastened to steel inserts embedded in the precast.

Stadia seating frames are mechanically fastened to ½" diameter bolt inserts embedded in the vertical portion of precast or cast-in-place risers.

To laterally stabilize the concrete frames and transfer lateral forces between the precast risers and the concrete frames, the steel embed plates at the ends of the risers are welded to the steel bearing plates cast in to the concrete frames.

Formed concrete ramps bearing on concrete masonry unit (CMU) walls provide access from the exterior to interior elevated bowl. The lower portion of the ramps are formed, cast-in-place tee shaped sections.

Mezzanines floors are constructed with 8ft wide precast double-tee sections spanning to cast-in-place girders supported by the main building columns.

The upper portions of the stadium, namely the east select seating and west press boxes are cast-in-place concrete with steel framed roof structure cantilevered out from the main column grid.

Two elevator towers were added for vertical transportation to upper levels. The towers are steel framed and clad with precast concrete panels.

The east elevator tower bridges over to the mezzanine office space.

Four steel stairs provide access to the ends of the mezzanine level. One additional steel stair provides access to the bridge linking the east elevator tower to the mezzanine level.

Various waterproofing and traffic coating systems have been applied to many areas of the precast risers in an attempt to prevent water from leaking into the occupied spaces on the ground and mezzanine floors below. In addition to the waterproofing/traffic coating applied to the top side of the precast, steel pan hard ceilings and gutters of various types and effectiveness have been installed on the underside.

The new north building was not included as a part of this condition assessment scope.

BGSU Doyt Perry Stadium, Bowling Green, Ohio/// FACILITY CONDITIONS ASSESSMENT

STRUCTURAL 04/11/13

DOCUMENT REVIEW:

Prior to carrying out the walk-through, a drawing review was conducted to understand the initial design and construction methodology.

The documents available are:

- Osborn-Papesh Architects – Engineers Drawings, Dated 07/30/65
- Schooley Caldwell Associates – Condition Assessment, Dated March 14, 2012, revised July 24, 2012
- Concrete Microscopy Inc – Petrographic Examination, Dated March 1, 2012

These documents provided valuable insight into the original construction design and details and some indication of issues that have been previously identified.

The Schooley Caldwell Associates and Concrete Microscopy Reports deal with the deterioration of the retaining wall at the low end of the stadia. This cast-in-place concrete wall is discussed in the body of this Report.

STRUCTURAL CONDITION ASSESSMENT:

Visible issues, deterioration and defects discovered during the condition assessment are highlighted with photographic references. These items are prioritized as short term (within 1 year), and future (within 5 years) time span within which the conditions need to be repaired.

Recommendations are made on the need for further destructive or non-destructive testing to determine the cause and extent of significant defects identified. Order of magnitude repair/rehabilitation costs are included for issues identified.

In general, the structure has been well maintained and in overall good condition. However, it is approaching 50 years in service and reaching the end of its original design life. There are a number of issues, related to the construction practices at the time of construction and available materials that are showing signs of significant deterioration and need to be addressed to extend serviceable life. As with all things, maintenance and remedial costs will escalate as the structure ages.

The general observed condition and issues that need to be addressed are detailed below for each building component.

PRECAST CONCRETE RISERS:

In general the precast concrete risers are in good condition showing minor deterioration, some minor cracking and spalling. With the exception of the embedded steel connection plates and load transfers elements. It appears that the embedded steel elements were lightly hot-dip galvanized or coated with a zinc-rich paint.

CLIP ANGLE CONNECTORS – RISER TO RISER:

Few connectors were found to be in near to original condition (refer to figure 42). However, majority of the connectors that connect precast risers together show signs of corrosion.



Figure 42- Steel Connector in Near to Original Condition

This coating over time has been depleted in the sacrificial galvanic reaction process to a beyond its protection, resulting in moderate to severe corrosion of the remaining steel. The extent of corrosion varies from minor to severe with all connectors on the exposed back side showing some signs of corrosion (refer to figure 43).

- *Comment: The extent of corrosion does not appear to be affecting the integrity of structure. Left untreated this condition will continue to deteriorate. There are over 8,000*

of these clip angles making it a costly and time consuming issue to address (future).

- *Testing: Desai/Nasr recommends removing two to five of these clip angles and their bolts to determine the condition of the bolts and inserts and rate of steel deterioration. Test results to be used to estimate the remaining life and what, if any, remedial measures are required to slow or stop this corrosion (short term).*



Figure 43- Steel Connector Typical Corrosion of Exposed connectors

STEEL END BEARING PLATES:

Steel plates and angle embeds in the ends of the precast risers and concrete frame transfer load from the precast riser to the concrete frame. These plates and angles are welded together to transfer lateral loads between members. The details are clearly illustrated on Osborn-Papesh drawings sheet S-3 (refer to figure 44).

BGSU Doyt Perry Stadium, Bowling Green, Ohio/// FACILITY CONDITIONS ASSESSMENT

STRUCTURAL 04/11/13




Figure 44- Precast Riser to Cast in Place Frame Typical Connection

During construction, steel shim stacks were used to level the precast risers and make up construction tolerances. These shim packs vary greatly in number and thickness of plates used. In an attempt to comply with the original details, the shim packs were welded together and to the embedded steel inserts. This steel assembly was observed to be moderately to severely corroded. The most severe corrosion was observed where the shim packs are high and/or where the shim plates were thin (refer to figure 45).



Figure 45- Corrosion at Thin Shim Plate - Welded completed Deteriorated



Figure 46- Corrosion of High Shim Stack - Note Rotation of Precast Beam

Rust jacking due to expansion of steel as it corrodes has broken most of the welds required to tie the structure together (refer to figure 46).

This condition occurs at over 2,000 locations.

The only location where no corrosion of the embedded plates was observed was at the expansion joint where the plates were not welded together (refer to figure 47).



Figure 47- No Corrosion at Expansion Joint - No Welds

- **Comment:** Rust jacking due to corroding steel plates is a major issue that needs to be dealt with. This condition is causing joint damage, resulting in increased water leaking through the structure, potential trip hazards as observed on the south east end, as well as compromising the integrity of the structure by leaving the components of the structure un-restrained or attached. Due to the number of locations, this single issue may be cost prohibitive to address. An order of magnitude cost estimate is possible only after the results of testing have been reviewed and possible repair solutions developed (short term).
- **Testing:** The extent and severity of the corrosion needs to be established to determine the best repair. At least 10 locations need to be tested showing varying states of deterioration. All rusted material should be removed to expose any remaining virgin steel or intact welding. Samples of the steel shim plates should be analyzed for chemical composition (short term).

PRECAST RISER JOINT SEALANT:

The horizontal and vertical joints between the precast risers are filled with polysulfide base hard sealant, according to the original drawings (refer to figures 48 and 49). The sealant observed in these joints appears to be mainly the original sealant, other than locations where various repairs and patches have been applied below layers of waterproofing and traffic coating.

BGSU Doyt Perry Stadium, Bowling Green, Ohio/// FACILITY CONDITIONS ASSESSMENT

STRUCTURAL 04/11/13



Figure 53- Waterproofing Membrane at Joint – Failure

Delamination, cracking and failure of the waterproofing membranes and applied traffic coating was observed through the structure (refer to figures 53, 54 and 55). In some areas the waterproofing is trapping water under the membrane allowing it to penetrate through the structure.

The area of elevated precast risers is estimated at around 78,000 sf.

Comment: To reduce the amount of water leaking through the structure into occupied spaces below and corroding the steel connections, a traffic coating is recommended to be applied to the entire top surface of the elevated precast risers and cast-in-place top slab areas. This work should only be carried out after all the other structural issues identified have been addressed (short term/future depending on severity of leaks).



Figure 54- Waterproofing Membrane at Precast Top - Failure



Figure 55- Applied Traffic Coating – Failure at Joint

CAST-IN-PLACE CONCRETE:

In general the cast-in-place concrete elements are in good condition for their age, with the exception of the lower bowl retaining walls and lower steps which is discussed in detail below.

MAIN LOAD BEARING FRAMES: Minor spalling of concrete due to insufficient cover to shear ties was observed at two elevated beams (refer to figure 56).



Figure 56 – Concrete Spalling at Main Frame Beam

Comment: Any loose or deteriorated concrete should be removed and exposed reinforcing bars cleaned of all rust. A corrosion inhibiting bonding agent should be applied to steel and concrete under new trowel applied mortar patch to restore adequate concrete cover (future).

SLABS AT TOP OF STADIA:

The top section of the stadia changes back from precast riser to a flat cast-in-place concrete slab. Cracking parallel to the span was observed consistently along the underside of this slab. The cracks do not appear to be affecting the durability or integrity of the structure at this time (refer to figure 57).

Ponding was observed on the north end of the east stadia. This ponding is penetrating the slab and freeze thaw action is breaking up the concrete slab and edge curb (refer to figure 58).

Comment: The deterioration of the concrete on the upper flat slab at the north east corner should be addressed (short term).

Testing: Desai/Nasr recommends petrographic analyses of two cores through the upper slab on the north east and south east

BGSU Doyt Perry Stadium, Bowling Green, Ohio/// FACILITY CONDITIONS ASSESSMENT

STRUCTURAL 04/11/13

corners to determine the condition of the concrete and type and extent of repair required (short term).



Figure 57- Shrinkage Cracking in Concrete



Figure 58- Deterioration of Slab and Curb

EXPOSED FRAME AT EMBEDDED STEEL PLATES:

Along the building expansion joint, the cast-in-place concrete frames column projects through the slab and is topped with an

embedded steel plate (refer to figure 59). The probable cause of this concrete deterioration is freeze/thaw cycling in concrete with no entrained air.



Figure 59- Deterioration of Exposed Concrete Column at Embed Plate

Comment: The damaged concrete should be removed and patched with a suitable trowel applied mortar.

STEEL BEAMS ENCASED IN CONCRETE AT UPPER BOXES:

The cantilevered roof framing of the upper boxes is structural steel. This steel is encased in concrete at the perimeter. Spalling of concrete due to insufficient cover was noted where the beam bears on the central column (refer to figure 60).

Comment: The damaged concrete should be removed, the exposed steel cleaned, a corrosion inhibiting bonding agent applied and area patched with a suitable trowel applied mortar (short term).



Figure 60- Spalling of Concrete Encasement at Embedded Steel Beam

BEAM SUPPORT CORBEL

In the concessions kitchen area below the west stadia a shear crack was observed in the corbel. This crack is a sign of shear failure (refer to figure 61).



Figure 61- Cracking and Failure of Corbel

BGSU Doyt Perry Stadium, Bowling Green, Ohio/// FACILITY CONDITIONS ASSESSMENT

STRUCTURAL 04/11/13

Comment: This crack is an indication of structural failure and needs to be addressed as soon as possible. The probable cause is improperly located shear reinforcing (short term).

Testing: Pacometer or penetrating Radar testing to determine location, configuration, size and number of reinforcing bars is recommended. This will determine the extent of repair required (short term).

LOWER BOWL SEATING AND RETAINING WALLS:

The lower bowl retaining wall deterioration (refer to figures 62 and 63) has been previously assessed in the Schooley Caldwell Associates Report and Concrete Microscopy Petrographic Examination. Visual observations and the review of these reports concludes that the wall is deteriorating due to breakdown of concrete due to combination of the effects of alkali-aggregate reactions, freeze/thaw cycles in low air content concrete and high permeability.

Alkali-aggregate reaction is an expansive chemical reaction between certain minerals found in coarse aggregate and the alkalis in Portland cement resulting in expansion, cracking and failure of the concrete matrix. Standard practice is to entrain air at a rate of approximately 6% for concrete, with 3/4 inch nominal aggregate, subjected to severe exposure. Air content was measured at 2% to 3% in the damaged portion of the wall.



Figure 62- Deterioration of Concrete Retaining Wall

PAGE 20



Figure 63- Deterioration of Concrete Return Walls

The Schooley Caldwell Associates Report presented four options for repairing the damaged wall. However, the report only addresses the lowest portion of the wall and horizontal slab to the first step.

Damage and deterioration of the concrete was also observed on the second and third riser of the stadia, the side retaining walls and steps down to the field (refer to figures 64 and 65).



Figure 64- Deterioration of Cast-In-Place Concrete Risers



Figure 65- Deterioration of Concrete Stair and Wall

Comment: The Schooley Caldwell Associates Report underestimates the extent of the repairs required to address this issue. Future modifications/enhancement of the stadia should consider reworking or re-constructing at least the front and side retaining walls as well as the first four rows of seating if not more of the lower bowl (short term).

SHRINKAGE CRACKING ON CORRIDOR LID:

Minor shrinkage cracking was observed in the cast-in-place concrete slab over the corridor between expansion joints (refer to figure 66). This cracking has no impact on structural integrity provided, water and de-icing salts do not penetrate into the concrete with the potential for damage due to corroding reinforcing bars.

BGSU Doyt Perry Stadium, Bowling Green, Ohio/// FACILITY CONDITIONS ASSESSMENT

STRUCTURAL 04/11/13



Figure 66- Shrinkage Cracking in Reinforced Concrete Slab

ACCESS RAMPS:

The sloping cast-in-place concrete access ramps are supported by CMU side walls. To form the slabs during construction light steel corrugated form deck was used (refer to figure 67). Over-time, this form deck has severely corroded and is peeling away from the concrete.



Figure 67- Delaminating steel Form Deck

PAGE 21

Comment: The peeling deck has no structural impact. However, from a safety standpoint the loose and damaged portions should be removed to prevent head injuries to people who access these areas used for storage (short term).

LIGHT POLE BASES:

Minor deterioration of the grout bed below the light pole base plates was observed. Cracking of the concrete base slab has occurred at one location (refer to figure 68).



Figure 68- Light Pole Support Base Cracking and Grout Deterioration

Comment: To prevent future damage, the deteriorated grout and damaged concrete should be removed and patched (short term).

EXTERIOR CONCESSION STRUCTURE:

Six precast concrete concession structures are located on the exterior of the stadia (refer to figure 69).

SLAB ON GRADE:

The slab on grade in all of the concession structures is cracked and showing signs of frost heave, resulting in potential trip hazards inside the area and at the access points.

Comment: Heaving concrete should be removed, fill below the slab should be replaced with frost resistant material before a new slab is cast (short term).



Figure 69- Frost Heave at Slab on Grade in Concessions

PRECAST CONCRETE:

In general the precast concrete is in good condition with some minor damage and deterioration due to: corrosion of embedded steel elements used to connect roof double-tees to column tees, cracking and spalling caused by corroding reinforcing (refer to figure 70).



Figure 70- Cracking of Concrete and Corrosion of Steel Embeds

BGSU Doyt Perry Stadium, Bowling Green, Ohio/// FACILITY CONDITIONS ASSESSMENT

STRUCTURAL 04/11/13

Comment: Cracking in the precast and corroding of steel should be addressed to extend the life of these structures and restore their aesthetic (future).

SEATING CONNECTION:

The design drawing shows steel inserts cast into the precast risers for attaching the vertical seat supports. Although the bolts used are not galvanized they appear to be in acceptable condition considering their age (refer to figure 71). Replacing seats may require a custom connection to take advantage of the existing embeds or the use of expansion or adhesive anchors.



Figure 71- Typical Seat to Precast Connection

STRUCTURAL STEEL STAIRS AND RAILS:

STAIRS:

The original steel stairs accessing the ends of the stadia are constructed of raised lug steel plate floor plate. Considering the age of the structure they are in reasonable condition. Minor steel corrosion and some concrete spalling at steel embedded connectors were observed at these stairs (refer to figure 72).



Figure 72- Minor Corrosion of Checkered Plate Stair

The newer stair on the east side that provides access to the bridge linking the elevator tower to the mezzanine offices is in very poor conditions. The composite metal floor deck is completely destroyed by corrosion. Most of the supporting steel members are showing signs of moderate to severe corrosion (refer to figure 73).



Figure 73- Severe Corrosion of Steel and Deck at Bridge Stair

Comment: Cleaning and patching of the original steel stairs and concrete will restore these elements and extend their serviceable life (future).

The newer stair needs to be removed and re-built to provide safe access to the bridge (short term).

GUARDRAILS:

Original steel guardrails along the north and south ends of the stadia are reaching the ends of their serviceable life. Corrosion of steel pipe rails and post members, joints base connections and welds is moderate to severe (refer to figures 74 and 75).



Figure 74- Split in Guardrail Top Rail

Various repairs and fixes have taken place. Most noticeable are the repairs to the base connections where new plate bracket have been expansion anchored to walls and curbs.

Comment: To ensure the guardrails comply with the code required strength to resist a point load of 200lbs or 50plf, we recommend that the guardrails are replaced or repaired (future).

Testing: Horizontal load test should be carried out to all the guardrails to determine the ability of the aging guardrail to rest the code specified loading (short term).

BGSU Doyt Perry Stadium, Bowling Green, Ohio/// FACILITY CONDITIONS ASSESSMENT

STRUCTURAL 04/11/13



Figure 75- Corrosion of Embed Plates and Steel Mesh Framing

CONCRETE MASONRY UNIT WALLS (CMU):

In general the CMU walls are in good condition throughout the structure.

Stepped cracking in two CMU bathroom divider walls were observed (refer to figure 76). The cracking appears to be caused by excessive deflection of the supporting structural members.



Figure 76- Stepped Crack in CMU Wall

PAGE 23

Moisture penetrating through the painted CMU wall was observed in the golf practice space (refer to figure 77). Water is leaking into the CMU from damaged or deteriorated control joint sealing along the edges of the concrete ramps supported by the wall. This moisture penetration could be occurring at more locations, but is highlighted here by the peeling paint.



Figure 77- Moisture Penetrating into CMU Wall From Above

Comment: Structurally, the cracks are minor and can be filled with a flexible sealant. If they are aesthetically un-acceptable then the tile will need to be removed. Additional vertical control joints cut into the CMU wall, the cracks repaired and wall re-tiled, with proper jointing (future).

Joint sealant along the sides of the concrete ramps should be ground out and replaced with suitable sealant to limit the amount of moisture penetrating into the supporting CMU walls (short term).

EXTERIOR NON-STRUCTURAL ELEMENTS:

WINDOWS AND WINDOW SEALANT:

The exterior window sealant is beyond serviceable life and is hard, cracked, peeling and non-existing in places (refer to figure 78).

Comment: Wall window sealant should be removed and replaced with a suitable flexible sealant (future).



Figure 78- Window Sealant Joint - Deteriorated

PRECAST PANELS:

The original drawings show the upper precast panels by-passing the exterior face of the cast-in-place concrete support members. Attachment of the panels is provided by short section of L2 1/2 x 2 1/4 x 1/4 angles field welded to embedded steel plates and angles.



Figure 79 - Bulge in Precast Panel

BGSU Doyt Perry Stadium, Bowling Green, Ohio/// FACILITY CONDITIONS ASSESSMENT

STRUCTURAL 04/11/13

Previous issues with the precast panel connections resulted in the removal of small exterior decorative panels and installation of new guardrails.

The remaining precast panels, the rear side of the elevated boxes, are in a better condition as the connectors are located inside and protected from corrosion. At one location on the west side a failed connection was observed with signs of the precast panel bulging outwards (refer to figure 79).

Comment: The attachment of the precast panels to the structure has limited redundancy. Failure of a single connection could result in a panel falling (short term).

Testing: Desai/Nasr recommends that all the steel connections attaching the precast panels to the structure be exposed, welds inspected by a qualified welding inspector and damaged or deficient welds or connections should be repaired as required (short term).

A crack in the precast window surround was observed at one location (refer to figure 80). This crack should be epoxy grouted to prevent further damage or deterioration.



Figure 80- Crack in Precast Window Surround

INTERIOR NON-STRUCTURAL ELEMENTS:

HARD PAN CEILINGS:

In the occupied mezzanine toilets, hard steel ceilings have been provided to protect the space from water leaking through the stadia risers. No insulation is provided above the hard ceiling and it appears that condensation due to a dew point induced by the steel ceiling is causing the paint to peel (refer to figure 81).



Figure 81- Humidity Corroding Underside of Hard Pan Ceiling

SPRAY ON INSULATION IN PRESS BOXES:

Spray-on thermal or sound insulation has been applied to the roof slab of the upper boxes. Water leaking through the roof into the insulation is causing discoloration and potential mold formation (refer to figure 82).

Comment: Leaks through the roof need to be fixed (future).

Testing: Discolored insulation should be tested for the presence of mold (short term).



Figure 82 - Mold/Discoloration of Spray on Insulation

STEEL MESH SUN SCREEN:

Minor rusting and corrosion of the plain steel mesh used to construct the sunscreen was observed (refer to figure 83). Regular maintenance and painting should extend its serviceable life.



Figure 83- Corrosion of Steel Mesh Sunscreen

BGSU Doyt Perry Stadium, Bowling Green, Ohio/// FACILITY CONDITIONS ASSESSMENT

STRUCTURAL 04/11/13

ELEVATOR TOWERS:

The precast panels surrounding the elevator towers appear in good condition (refer to figure 84).



Figure 84- Elevator Tower



Figure 85- High Roof Membrane

ROOFING:

The high roofs above the boxes areas appear to be sound with no signs of cracking, delamination or hardening. There are areas underfoot that appeared soft and/or bulging (refer to figure 85).

Comment: Soft spots in the roofing along with signs of leaking due to discoloration of spray-on material indicate the need for further investigation (future).

Testing: The membrane roofing should be inspected by a qualified roofing specialist to determine the need for repairs and remaining serviceable life (short term).

BGSU Doyt Perry Stadium, Bowling Green, Ohio/// FACILITY CONDITIONS ASSESSMENT

STRUCTURAL 04/11/13

TESTING REQUIREMENTS

Structural Element	Test Type	Location	Number	Remark
Steel Clip Angle and Bolt Connecting Precast Risers	Determine Severity of Steel Corrosion	Underside of precast risers - Both Stadia	5	Remove existing clips and connecting bolts in varying condition, remove all rusted material and measure thickness of remaining virgin steel.
Embedded Steel Elements and Shim Plates at Precast Riser to Cast-in-Place Frame Connection	Determine Severity of Steel Corrosion and composition/quality of steel shim plates.	Ends of precast risers - Both Stadia	10	Remove all corrosion from embed plates and shim plate and measure size and thickness of remaining virgin steel. Take three samples of steel shim plates and determine their chemical composition. These shim plates appear to be corroding at an accelerated rate.
Cast-in-Place Concrete Slab deterioration	Petrographic Analysis of Concrete	Cast-in-place concrete slab at top of Stadia. Take cores through slab at north and south ends of east stadia.	2	
Failing Cast-in-Place Concrete Corbel	Pacometer or Penetrating Radar to determine size and location of shear reinforcing bars.	Corbel in concessions preparation area.	1	
Steel Guard Rail	Horizontal Load Test	Side rails at edges of stadia.	6	Apply incremental loads up to 1.6 times the code specified point load. Stop test if any signs of excessive deflection or failure is observed. Measure deflection under load and after load has been applied to verify elastic load transfer.
Steel Clip Angles Supporting Elevated Precast Panels	Visual observation of Connection	Alleviated original precast panels at upper press boxes - Both Stadia		Expose and visually observe condition of all steel connections. Report any signs of deterioration, cracking or failure.
Spray on material	Test discoloration of spray on material for signs of dangerous mold.	Underside of slabs at press boxes - Both Stadia	4	
Roof Membrane	Visual and adhesion test of roofing	High roof areas - Both Stadia	3 Areas	Inspection of roofing material by specialist to determine condition, remaining life and repair work required.